

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATION	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT - " (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator Lynx Petroleum Consultants, Inc.		8. Farm or Lease Name Geraldine Doughty
3. Address of Operator P. O. Box 1666, Hobbs, NM 88241		9. Well No. 1
4. Location of Well UNIT LETTER <u>K</u> , <u>2100</u> FEET FROM THE <u>West</u> LINE AND <u>1650</u> FEET FROM THE <u>South</u> LINE, SECTION <u>25</u> TOWNSHIP <u>16S</u> RANGE <u>36E</u> NMPM.		10. Field and Pool, or Wildcat Lovington (Paddock) Undesignated (Queen)
15. Elevation (Show whether DF, RT, GR, etc.) 3855' DF		12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <u>Downhole Commingling</u> <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

05/30/86 Pld rds, pump & tbg. Set tension pkr @ 3857'. Ran tracer survey. POOH w/pkr. PU ret tool. Wash hole clean to BP. Pld BP. Ran pump & rds. Started well ppg.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Jerry W. Sexton TITLE Vice-President DATE 06/02/86

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY JERRY SEXTON TITLE DISTRICT I SUPERVISOR DATE JUN 9 1986

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED
JUN 6 1986
270
HOBBS OFFICE