

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-73

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

30-025-23893

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-	7. Unit Agreement Name
2. Name of Operator Getty Oil Company	8. Farm or Lease Name Lovington Lumpkin "20
3. Address of Operator P. O. Box 728, Hobbs, New Mexico 88240	9. Well No. 1-X
4. Location of Well UNIT LETTER I, 1980 FEET FROM THE South LINE AND 660 FEET FROM THE East LINE, SECTION 20 TOWNSHIP 16-S RANGE 37-E NMPM.	10. Field and Pool, or WHdout N.E. Lovington Penn
15. Elevation (Show whether DF, RT, GR, etc.) 3808.1' (GR)	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TOTAL DEPTH 11,600'
13 3/8" OD 48# H-40 CSG SET @ 460'
8 5/8" OD 20# & 24# K-55 & N-80 CSG SET @ 4504'

1. Spot 45 sx. Cement plug from 11,583-11,433'.
2. Spot 45 sx. Cement plug from 11,315-11,155'.
3. Spot 45 sx. Cement plug from 10,875-10,725'.
4. Spot 45 sx. Cement plug from 8460-8310'.
5. Spot 45 sx. Cement plug from 7795-7645'.
6. Spot 45 sx. Cement plug from 6425-6275'.
7. Spot 45 sx. Cement plug from 5042-4892'.
8. Spot 45 sx. Cement plug from 4573-4423'.
9. Spot 45 sx. Cement plug from 2340-2190'.
10. Spot 45 sx. Cement plug from 534-398'.
11. Spot 100' Cement plug from 100'-Surface.
12. Install Dry Hole Marker. Clean Location well Plugged & Abandoned 10-24-84.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED W.A. Baker II TITLE Dist. Opr. Mgr. DATE 1-31-85
APPROVED BY Ronald M. Cullberg TITLE OIL & GAS INSPECTOR DATE AUG 30 1985
CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

FFR - 5 1985

O.C.D.
HOBBS OFFICE