

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

**OIL CONSERVATION DIVISION**  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-28905
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. IG-2252
7. Lease Name or Unit Agreement Name Kochia AAM State
8. Well No. 1
9. Pool name or Wildcat Dean Devonian

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	Name of Operator YATES PETROLEUM CORPORATION
Address of Operator 105 South Fourth Street - Artesia, NM 88210	Well Location Unit Letter <u>0</u> : <u>990</u> Feet From The <u>South</u> Line and <u>2310</u> Feet From The <u>East</u> Line Section <u>35</u> Township <u>15S</u> Range <u>36E</u> NMPM Lea County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3855.1' GR	

1. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
<b>NOTICE OF INTENTION TO:</b>	<b>SUBSEQUENT REPORT OF:</b>
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER: <input type="checkbox"/>	OTHER: Abandon perforations <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

12-29-93 - Moved in and rigged up pulling unit. POOH with subpump and cable. RIH with retrieving tool. Picked up 2-7/8" tubing. Catch RBP at 13656' - open K valve. Equalize. POOH. Shut down for night.  
12-30-93 - TIH w/4-3/4" OD string mill, and drill collars. Milled DV tool at 12834'. POOH. Lay down drill collars and mill. Shut down for night.  
12-31-93 - RIH w/4-3/4" bit to 13710.53'. POOH. Shut down for night.  
1-3-94 - Rig up wireline. RIH w/4-3/4" gauge ring and junk basket. POOH. RIH w/CIBP and set at 13654'. Dumped 4' of cement on top of CIBP. Shut down for 48 hours.  
1-5-94 - TIH w/5-1/2" 17# Uni V packer. Tag cement top at 13650'. Set packer at 13643'. Tested to 1000 psi for 15 minutes, OK. Swabbed to seating nipple. POOH.  
1-6-94 - Returned to production from perforations 13594-13598'.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Rusty Klein TITLE Production Clerk DATE 8-2-94  
TYPE OR PRINT NAME Rusty Klein TELEPHONE NO. 505-748-1471

(This space for State Use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_