## STATE OF NEW MEXICO RGY AND MINERALS DEPARTMENT

HOT WING WINGLANDS DE	 
DISTRIBUTION	
SANTA FE	 ↓
116	 ┼
U.S.O.S.	 ┼
LAND OFFICE	 ┼
DPERATOR	 

## OIL CONSERVATION DIVISION P. O. BOX 2088

Form C-103 - Revised 10-1-78

DISTRIBUTION	P. O. 60%			
SANTA PE	SANTA FE, NEW	MEXICO 87301	Sa. Indicate Type of Lease	
FILE		State X Fee		
V.S.O.S.		•	5. State Oil & Gas Lease No.	
LAND OFFICE			LG 2251	
OPERATOR			LG 2231	
CL IN IO DV	NOTICES AND REPORTS ON	WELLS		
SUNUK T	SALS TO DRILL OR TO DEEPEN OR PLUE BA	PROPOSALS.)	7. Unit Agreement Name	
(BO MOT USE THIS PORM FOR PROPERTION	a FOR PERMIT (FORE		7. Ohit Agreement Italia	
OIL X WELL OTHER-		8. Farm of Lease Name		
		Lea VP State		
Name of Operator Yates Petroleum Cor	moration		9. Well No.	
		1		
Address of Operator		·		
207 South 4th St., Artesia, NM 88210			10. Field and Pool, or WHdcat	
4 14 - 11		1.000	Wildcat (Saunders)	
C 660 PEET PROM THE NORTH LINE AND 1980 PEET PROM			minimum "	
UNIT LETTER	C 660 PEET PROM THE THE LINE AND			
Unit CELLEN AMERICA	32	5S 33E		
West		RANGEHMP		
THE LINE, SECTIO	)N		12. County	
	15. Elevation (Show whether	DF, RT, GR, etc.)	Lea	
	4203.	5' GR	ьеа (((()))	
		Denne on (	Ocher Data	
S. Check	Appropriate Box To Indicate I	Nature of Notice, Report of	OUT DEBORT OF	
Cneck A	TO TO	SUBSEQUE	NT REPORT OF:	
NOTICE OF IN	TENTION TO:			
	<b>ر</b> ـــ	REMEDIAL WORK	ALTERING CASING	
	PLUG ILNO ABANDON	,, , , , , , , , , , , , , , , , , , , ,	PLUE AND ABANDONMENT	
PERFORM REMEDIAL WORK	•	COMMENCE DRILLING OPHS.		
TEMPORARILY ABANDON	CHANGE PLANS	CASING TEST AND CEMENT JOS	x X	
PULL OR ALTER CASING	CHANGE FEAT	Perforate, Tre	eat	
	<u></u>	1	•	
		J (		
MARK.		i - perioant dates, inclus	ding estimated date of starting any proposed	
Durant of Completed O	perations (Clearly state all pertinent de	etails, and give pertuted accept me	ding estimated date of starting any proposed	
<b>-</b> ,,			12/6/-72' w/2000 gals	
1 2 05 WIH and n	perforated $12\dot{4}64-72$ ' w/1	0 .50" holes. Acidized	12404 /2	
1-3-85. WIH and perforated 12464-72' w/10 .50" holes. Acidized 12464-72' w/2000 gals				
7½% Morflo acid ar	IG NZ.	•		
	11 1 0	f and no oil.		
1-6-85. Recovered load with small show of gas, no oil.				
1 0 000			TCE 109903 TT/23 45"	
T T OF CAL CIPD	at 11000' w/35' cement.	WIH and perforated 10	1/65-10609 W/25 145	
1-/-85. Set Clbr	10765 66 69 70, 108	10, 11, 12, 13, 14, 15,	23, 24, 25, 26, 55, 50,	
holes as follows:	10/65, 00, 05, 70, 200	<b>10</b> ,,	23, 24, 25, 26, 55, 56,	
57, 72, 73, 74, 8	/, 88 and 09 ·			
			Acidized in 3 stages	
1 0 05 0-4 200	er below all perfs and t	ested CIBP. Plug held.	ACTUIZED IN 5 SCORES	
1-8-85. Set pack	er below all perfs and tell to the series of the series and tell tell tell tell tell tell tell tel	355-89'(9 shots) w/2000	gals 15% NEFE acid,	
as follows: Stag	e 1: Acidized peris 100	and parfs 10810-26' (10	) shots) w/2000 gals 15%	
+ 2% KCL. 9 ball s	ealers. Stage 2: Acid	ized peris 10010 20 (1	) shots) w/2000 gals 15% 0765-70' (4 holes) w/1000	
NEEE acid 2% KCI.	+ 9 ball sealers. Stas	ge 3: Acidized peris it	0765-70' (4 holes) w/1000 k - recovering load.	
HELE GCIG, 2% ROD	. + 9 ball sealers. Stag d, 2% KCL. No ball sea	lers. Flowing well back	r - Tecovering Toda.	
gais 13% Nere act	, 2/0 2021			
	•		,	
•	•		·	
		4.5.41.4		
	ien above is true and complete to the b	est of my knowledge and belief.		
18. I hereby certify that the informati	7			
· · · · · · · · · · · · · · · · · · ·	1		1-9-85	
$\sim$ $\sim$ $\sim$	•	Droduction Supervisor	DATE / V2	
· Our part	) on lett rire.	Production Supervisor	OAYE _	
Juanta	) os lett vine	Production Supervisor	[ABI 4 > 400F	
Juanta	DAN LETT HITE	Production Supervisor	JAN 1 5 1985	
ORIGINAL SIGNER	D BY JERRY SEXTON SUPERVISOR TITLE	Production Supervisor	JAN 1 5 1985	