

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	State ☒ Fee ☐
----------------------------	--

5. State Oil & Gas Lease No.	B-9683
------------------------------	--------

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. Unit Agreement Name
2. Name of Operator Conoco Inc.	8. Farm or Lease Name Andersen Ranch Unit
3. Address of Operator P.O. Box 460 - Hobbs, New Mexico 88240	9. Well No. No. 19
4. Location of Well UNIT LETTER <u>L</u> , <u>2080</u> FEET FROM THE <u>south</u> LINE AND <u>660</u> FEET FROM THE <u>west</u> LINE, SECTION <u>11</u> TOWNSHIP <u>16S</u> RANGE <u>32E</u> NMPM.	10. Field and Pool, or Wildcat Andersen Ranch Wolfham
15. Elevation (Show whether DF, RT, GR. etc.)	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐
OTHER ☐

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOB ☐
OTHER ☐

ALTERING CASING ☐
PLUG AND ABANDONMENT ☒
OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

MIRU. Tag CIBP at 9697'. Spot 12 sxs class "C" cement on top of CIBP at 9597'-9697'. Pumped 135 bbls 10" brine. Spot 12 sxs class "C" cement over 4165'-4265'. Pumped 40 bbls 10" brine. POOH w/ hbg. Spot 12 sxs class "C" cement from 2380'-2480'. Pumped 25 bbls 10" brine. POOH w/ hbg. Spot 12 sxs class "C" cement from 1305'-1405'. Pumped 20 bbls 10" brine. POOH w/ hbg. Spot 12 sxs cement from 505'-605'. Pumped 12 bbls 10" brine. Circulate to surface. Cut off well head. Spot 6 sxs cement from 0'-50'. Install P&A marker.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED DE FINNEY TITLE Administrative Supervisor DATE August 19, 1987

APPROVED BY [Signature] TITLE OIL & GAS INSPECTOR DATE JAN 26 1988

CONDITIONS OF APPROVAL, IF ANY:
NMACD-Hobbs(3) File

E