

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

**OIL CONSERVATION DIVISION**  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO.	3002529158
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	B-11454
7. Lease Name or Unit Agreement Name	
Eddy Lea State NCT-B Com.	
8. Well No.	1
9. Pool name or Wildcat	
Anderson Ranch Wolfcamp, N.	

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	
2. Name of Operator Hondo Oil & Gas Company	
3. Address of Operator P. O. Box 2208, Roswell, NM 88202	
4. Well Location Unit Letter <u>L</u> : <u>3600</u> Feet From The <u>North</u> Line and <u>660</u> Feet From The <u>West</u> Line Section <u>2</u> Township <u>16S</u> Range <u>32E</u> NMPM Lea County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
<b>NOTICE OF INTENTION TO:</b>	<b>SUBSEQUENT REPORT OF:</b>
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

2/18/92 RU unset TAC SN 9700'.  
2/19/92 Spotted 30 sx Class "H" cmt @ 9600', tagged top of cmt @ 9321', spotted 20 sx Class "C" cmt @ 5670'.  
2/20/92 Free point 5 1/2" csg @ 2575', Spotted 30 sx Class "C" cmt to 3920', tag plug w/wireline @ 3950', cut 5 1/2" csg @ 2585'.  
2/21/92 Pumped 40 sx Class "C" cmt 2635', tag w/ Wireline @ 2505', spotted 30 sx Class "C" cmt 1560' to 1460', spotted 30 sx Class "C" cmt 554'-454'. Spotted 10 sx Class "C" cmt to surface. Cut off wellhead & install dry hole marker.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE E. L. Buttross Jr. TITLE Petroleum Engineer DATE 03/11/92  
TYPE OR PRINT NAME E. L. Buttross, Jr. TELEPHONE NO. 625-6732

(This space for State Use)  
**ORIGINAL SIGNED BY RAY SMITH**  
**FIELD REP. II**

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY:

**OIL & GAS INSPECTOR**

**JUL 27 '92**

RECEIVED

MAR 13 1992

CCD HOBBS OFFICE