

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO.  
3002529158

5. Indicate Type of Lease  
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.  
B-11454

7. Lease Name or Unit Agreement Name

Eddy Lea State NCT-B Com.

8. Well No.

1

9. Pool name or Wildcat

Anderson Ranch Wolfcamp, N.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:  
OIL WELL ☒ GAS WELL ☐ OTHER

2. Name of Operator  
Hondo Oil & Gas Company

3. Address of Operator  
P. O. Box 2208, Roswell, NM 88202

4. Well Location  
Unit Letter L : 3600 Feet From The North Line and 660 Feet From The West Line

Section 2 Township 16S Range 32E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plugging Procedure Approved by Jerry Sexton on 9-24-91.

13 3/8" csg @ 504' cmt circ'd  
8 5/8" csg @ 4180 cmt circ'd  
5 1/2" csg @ 10,750' (calc'd TOC @ 3650')  
Perfs 9680'-9686'.

- (1.) Set CIBP @ 9600' w/ 35' cmt on top.
- (2.) Spot 20sx cmt plug @ top of Glorieta @ 5670'.
- (3.) Free pt 5 1/2" csg & jet cut @  $\pm$  3500'.
- (4.) Spot 100' cmt plug over 5 1/2" csg stub.
- (5.) Spot 100' cmt plug @ Top of Salt @ 1560'.
- (6.) Cut off wellhead & install 10sx surface plug.

- (7.) Install dryhole marker.  
Est. date to start 10/15/91.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE E. L. Buttross Jr. TITLE Petroleum Engineer DATE 09/30/91  
E. L. Buttross, Jr. (505) 625-6732  
TYPE OR PRINT NAME TELEPHONE NO.

(This space for State Use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY: