

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

U.S. CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. E-3788	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-		7. Unit Agreement Name
2. Name of Operator Chevron U.S.A. Inc.		8. Farm or Lease Name Lea "CS" State (NCT-A)
3. Address of Operator P.O. Box 670 Hobbs, NM 88240		9. Well No. 1
4. Location of Well UNIT LETTER <u>B</u> <u>660</u> FEET FROM THE <u>North</u> LINE AND <u>1650</u> FEET FROM THE <u>East</u> LINE, SECTION <u>10</u> TOWNSHIP <u>16S</u> RANGE <u>32E</u> N.M.P.M.		10. Field and Pool, or Wildcat Anderson Ranch Wolfcamp
15. Elevation (Show whether DF, RT, GR, etc.) 4313 GL		12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input checked="" type="checkbox"/> TA Lower Wolfcamp Perfs and Perfprate Upper Wplfcamp

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Set CIBP @ 9840 and test to 1000psi for 30 minutes. Perforate from 9493-9700.
Acidize as necessary. Return to production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>P. H. Bullock Jr.</u>	TITLE <u>Division Drilling Manager</u>	DATE <u>1-9-1986</u>
APPROVED BY <u>Eddie W. Seay</u> <u>Oil & Gas Inspector</u>		
TITLE _____ DATE <u>JAN 10 1986</u>		
CONDITIONS OF APPROVAL, IF ANY:		

RECEIVED

JAN 10 1986

O.C.D.
HOLDS OFFICE