Form	C-103
Revis	ed 1-1-8

FEE L

Line

State of New Mexico Submit 3 Copies Energy, Minerals and Natural Resources Department to Appropriate
District Office OIL CONSERVATION DIVISION DISTRICTI WELL API NO. P.O. Box 1980, Hobbs, NM 88240 35 -025-P.O. Box 2088 Santa Fe, New Mexico 87504-2088 **DISTRICT II** 5. Indicate Type of Lease P.O. Drawer DD, Artesia, NM 88210 6. State Oil & Gas Lease No. 1000 Rio Brazos Rd., Aztec, NM 87410 **V**-496 SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A 7. Lease Name or Unit Agreement Name DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) Type of Well: State H OTHER WELL 8. Well No. 2. Name of Operator Mewbourne Oil Company 9. Poor name or Wildcat 3. Address of Operator P.O. Box 5270 Hobbs, New Mexico 88240 Hume Wolfcamp 4. Well Location East 1040 North 660 Feet From The Feet From The Line and

	Section	7		Township	16S	Ran		34E	NMPM		Lea	C	County
				10. Ele	vation (Show w 4149.0'		OF, RKB	RT, GR, etc.,)				
11.	N(Theck App	-		cate N	Vature		e, Report, o			OF:	
PERFOR	M REMED	IAL WORK		PLUG AND	ABANDON		REME	DIAL WORK	ζ		ALTERING C	ASING	
TEMPOR	ARILY AB	ANDON		CHANGE P	LANS		COMI	MENCE DRIL	LING OPNS.		PLUG AND A	ABANDONN	IENT _
PULL OF	ALTER C	ASING					CASIN	IG TEST AN	D CEMENT JC	в			
OTHER:							OTHE	R:					
work -	Set CI	E 1103. 5 1/2" + BP at +		o abando	n Wolfca		erf's		including estima				ent.

* Note: Records show long string cemented to surface. If it determined that there is recoverable casing, we will cut it off and notify the NMOCD.

- Set 100' plug at $46\overline{3}5$ ' (8-5/8" casing set at 4585'). Tag plug.

			4 DD A 4 400
TYPE OR PRINT NAME	Erick W. Nelson		TELEPHONE NO.
SIONATURE 4	IW. Der	Engineer	03/28/94 DATE
I hereby certify that the it	aformation appropriations and complete to the best of my	knowledge and belief.	00/00/0/
160	overable casing, we will e	,	

ORIGINAL SIGNED BY JERRY SEXTON

APR **U1** 1994

- DATE -

DISTINGY I SUFERVISOR

- TITLE -

" NDITIONS OF APPROVAL, IF ANY:

(This space for State Use)

A PROVED BY ---

- Set 100' plug at 1000'.

- Cut off wellhead and set 10 sx. plug. - Install P & A marker and clean location.