

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
E-1075

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-	7. Unit Agreement Name
2. Name of Operator Bliss Petroleum, Inc.	8. Farm or Lease Name ARCO STATE
3. Address of Operator P. O. Box 1817 Hobbs, NM 88240	9. Well No. 1-Y
4. Location of Well UNIT LETTER <u>E</u> <u>2310</u> FEET FROM THE <u>North</u> LINE AND <u>930</u> FEET FROM THE <u>West</u> LINE, SECTION <u>35</u> TOWNSHIP <u>15S</u> RANGE <u>36E</u> NMPM.	10. Field and Pool, or Wildcat Dean Devonian
15. Elevation (Show whether DF, RT, GR, etc.) GR 3861.5, KB 3880	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input checked="" type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Spudded @ 8:45 AM, 6-30-85

MIRU Rotary Rig. Drld. 26" hole to 218'. Set new 20", 169# csg. @ 217' and cmt'd w/575 sx Cl'C" + 1/4 cello-seal/sk + 2% CaCl₂. Circ. 330 sx to surf. PD & JC @ 6:04 PM, 6-30-85. Did not bump plug. WOC 6 hrs. & rlse press. Cut-off 20" & weld on flow nipple. Press. tst. 20" to 500 PSI for 30 mins. - OK. WOC total of 12 hrs. before drlg. out.

M. WOC - 18 HRS

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Paul Bliss</u>	TITLE <u>President</u>	DATE <u>7-2-85</u>
ORIGINAL SIGNED BY JERRY SEXTON DISTRICT 1 SUPERVISOR		
APPROVED BY _____	TITLE _____	DATE <u>JUL 3 1 1985</u>
CONDITIONS OF APPROVAL, IF ANY:		