

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION

P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. E-1075	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-		7. Unit Agreement Name
2. Name of Operator Bliss Petroleum, Inc.		8. Farm or Lease Name ARCO State
3. Address of Operator P. O. Box 1817 Hobbs, N.M. 88240		9. Well No. 1-Y
4. Location of Well UNIT LETTER <u>E</u> <u>2310</u> FEET FROM THE <u>North</u> LINE AND <u>930</u> FEET FROM THE <u>West</u> LINE, SECTION <u>35</u> TOWNSHIP <u>15S</u> RANGE <u>36E</u> N.M.P.M.		10. Field and Pool, or Wildcat Dean Devonian
15. Elevation (Show whether DF, RT, GR, etc.) GR 3861.5, KB 3880		12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input checked="" type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Drld. 17 1/2" hole to 2065'. Could not get below 2053'. Ran 53 jts. new csg. as follows:

1 - Western Texas Pattern Shoe (notched)	0.98
1 - jt. csg., 13 3/8", 61# K-55, ST&C, 8RT	35.81
1 - Western Float Collar	1.50
1 - jt. csg., 13 3/8", 61# K-55, ST&C PIN X BT&C BOX	35.07
51 - jts. csg., 13 3/8", 61# K-55 BT&C	2011.67
Total Run	2085.03
Landed Above KB	-32.63
Set At	2052.40

RU Western. Cmt. w/ 1400 sks. Pacesetter Lite "C" w/ 1/4 #/sk. Cello-Seal & 2% CaCl<sub>2</sub> followed w/ 200 sk. Class "C" neat. Displ. w/ 310 BFW. Plug dwn. @ 11:32 PM on 7-4-85. Rel. press. & Float held OK. Circ. 323 sks. to surface. WOC 12 hrs. Press. tested csg. to 1000#. Held OK 30 min.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Paul Bliss TITLE President DATE 7-9-85  
ORIGINAL SIGNED BY JERRY SEXTON  
APPROVED BY DISTRICT 1 SUPERVISOR TITLE \_\_\_\_\_ DATE JUL 31 1985  
CONDITIONS OF APPROVAL, IF ANY: