

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease

State ☒ Fee ☐

5. State Oil & Gas Lease No.
LG9178 & V-1441

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name State "5"
2. Name of Operator Adobe Resources Corporation	8. Farm or Lease Name State "5"
3. Address of Operator 300 W. Texas, Suite 1100, Midland, Tx. 79701	9. Well No. 1
4. Location of Well UNIT LETTER <u>M</u> <u>660</u> FEET FROM THE <u>South</u> LINE AND <u>660</u> FEET FROM THE <u>West</u> LINE, SECTION <u>5</u> TOWNSHIP <u>15-S</u> RANGE <u>35-E</u> NMPM.	10. Field and Pool, or Wildcat Morton Lower Wolfcamp
15. Elevation (Show whether DF, RT, GR, etc.)	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 4/28/87: GIH w/tbg. Set packer @ 10,360'. Acidize perfs (10,522-82') w/1500 gals. 15% NEFE acid.
- 4/30/87: SITP 10#. FL 7400'. Swab 55 BF 20% oil. FFL 9500'. NU BOP. POH w/tbg and packer.
- 5/4/87: Perforate 9945-48' (5 holes). GIH w/RBP & packer and tbg. Set plug @ 10,056', pkr @ 9850'. Acidize w/1000 gals 15% NEFE 1.5 BPM 6500#.
- 5/6/87: Acidize perfs (9945-48') w/2000 gals. 28% NEFE, 2.8 BPM @ 6400#. Swab 20 BLW. Re-trieve plug & return well to pumping status.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Lonnie Arnold TITLE Lonnie Arnold, Engineer DATE 7/7/87

ORIGINAL SIGNED BY JERRY SEXTON

APPROVED BY DISTRICT I SUPERVISOR TITLE DATE JUL 10 1987

CONDITIONS OF APPROVAL, IF ANY: