

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I

P.O. Box 1980, Hobbs NM 88241-1980

DISTRICT II

P.O. Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-29415
5. Indicate Type of Lease	STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name	
ANDRUS 9	
8. Well No.	1
9. Pool name or Wildcat	N.E. LOVINGTON PENN

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	
2. Name of Operator Amerada Hess Corporation	
3. Address of Operator P. O. Drawer D, Monument, NM 88265	
4. Well Location Unit Letter <u>L</u> : <u>1874</u> Feet From The <u>SOUTH</u> Line and <u>766</u> Feet From The <u>WEST</u> Line Section <u>9</u> Township <u>16S</u> Range <u>37E</u> NMPM <u>LEA</u> County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3823' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

4-1 thru 4-9-96

MIRU Sierra Well Svc. Bled down press., removed wellhead & install BOP. TOH w/tbg. & TAC. TIH w/CIBP & set at 11,444'. Circ. csg. volume w/plugging mud. Spot 25 sks. cement on top of CIBP at 11,444'. Spot 30 sks. cement fr. 9000' - 8800'. Spot 30 sks. cement fr. 6500' - 6250'. Spot 30 sks. cement fr. 5135' - 4875'. Jet cut 5-1/2" csg. at 4350' & TOH w/50 jts. 5-1/2" csg. TIH w/tbg. to 4396' & pumped 40 sks. Class C cement. WOC for 3 hrs. & tagged plug at 4209'. Spot 40 sks. cement fr. 2250' - 2120'. Spot 40 sks. cement fr. 550' - 430'. Spot 10 sks. cement surface plug. RDMO plugging unit. Cut off wellhead & installed dry hole marker. Cut off deadman anchors & cleaned location. Well plugged & abandoned.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE R. L. Wheeler, Jr. TITLE Admin. Svc. Coord. DATE 4-22-96
TYPE OR PRINT NAME R. L. Wheeler, Jr. TELEPHONE NO. 505 393-2144

(This space for State Use)

APPROVED BY [Signature] TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY: _____