

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-29566
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	K-5187

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. Name of Operator
Pennzoil Exploration & Production Company

3. Address of Operator
P. O. Box 8850 - Midland TX 79708-8850

4. Well Location
Unit Letter L : 1400 Feet From The South Line and 660 Feet From The West Line
Section 17 Township 16S Range 37E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
3844 GR - 3862 RKB

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

10/01/92: Set 5-1/2" CIBP at 11300' with 35' cement on top - (Top Cement at 11265').
10/02/92: Load hole with 10# mud.
10/05/92: Could not pull casing free - Stuck from 8000' to 5600' - Call NMOC for OK to cut casing at 5406' - Approved by Mr. Jerry Sexton.
10/06/92: Pumped 25 sx cement plug at 6416' inside 5-1/2" casing - Top cement at 6216'.
10/08/92: Cut 5-1/2" casing at 5406' - Pulled 130 jts. of 5-1/2" casing.
10/10/92: Went in hole open-ended with 2-7/8" tubing to 5476' - Set 50 sack plug - Tagged plug at 5282' - Pulled up to 4293' & set 50 sack plug.
10/12/92: Tagged top of cement at 4086' - Pump 25 sack plug 4086' back to 3997' - Pulled up to 2137' - Set 35 sack plug - Pulled up to 476' & set 35 sack plug - Pulled out of hole & set 10' surface plug.
10/13/92: Dug out well head - Cut off 8-5/8" flange - Weld on Dry Hole Marker - Fill in well head - Dig out anchors & cut off same - Clean trash off of location - Well is P & A on 10/13/92 - " FINAL REPORT ".....

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Roy R. Johnson TITLE Sr. Accountant DATE October 26, 1992
TYPE OR PRINT NAME Roy R. Johnson 915-689-8907 TELEPHONE NO.

(This space for State Use)

APPROVED BY F. M. L. L. L. TITLE OIL CONSERVATION DIVISION DATE FEB 25 1993
CONDITIONS OF APPROVAL IF ANY: