

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. V-340	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Dry Hole		7. Unit Agreement Name NA
2. Name of Operator Mabee Petroleum Corp.		8. Farm or Lease Name State 'AH'
3. Address of Operator 400 W. Illinois, Suite 1500 Midland, TX 79701		9. Well No. 1
4. Location of Well UNIT LETTER C, 660 FEET FROM THE north LINE AND 1980 FEET FROM THE west LINE, SECTION 15 TOWNSHIP 16S RANGE 37E NMPM.		10. Field and Pool, or Wildcat Lovington Penn. N.E.
15. Elevation (Show whether DF, RT, GR, etc.) 3795' GR		12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

8/21 Rig up pulling unit. N.D. wellhead & POOH w/tubing.
8/22 Finished POOHw/ tbg & pkr. RIH w/wireline & CIBP to 10677' & lost CIBP & setting tool. P.U. fishing tools & RIH w/tbg.
8/23 Finished RIH w/tbg to 10677'. Worked w/CIBP @10677' & could not move up or down. POOH & recovered W/L setting tool. Left CIBP @10677.
8/24 SD on Sunday.
8/25 RIH w/tbg to 10677' & spotted 15sxsClass "H" cement plug on top of CIBP. Circ hole w/10 ppg gelled mud. After 3 hrs RIH & tagged TOC plug @10544. POOH w/10 stds tub.
8/26 Finished POOH w/tbg. Found free point on 5-1/2" casing @±6000'.
8/27 RIH w/tbg & spotted 20 sx Class "H" cmt plug @9641'. Spotted 20 sx Class "H" cmt plug @8100'. POOH w/30 jts. tbg.
8/28 SD due to weather.
8/29 Finished POOH w/tbg. Cut 5-1/2" csg @6500'. POOH & L.D. 60 jts 5-1/2" casing.
8/30 thru 9/1 Shut-down.
9/2 Finished RIH w/tbg to 6553'. Pumped 35 sx Class "H" cmt as plug from 6553-6400'. Pull 30 stds tbg. SD for 4 hrs. RIH & tagged cmt plug at 6390'. POOH w/tbg to 4425' pumped 35 sx Class "H" cmt plug from 4425-4306'. POOH w/30 stands tbg. SD.

See Reverse Side -

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED — <u>W. T. Thomas</u>	TITLE — <u>Engineering Manager</u>	DATE — <u>9/8/86</u>
APPROVED BY <u>[Signature]</u> TITLE <u>OIL</u> DATE <u>9/8/86</u>		
CONDITIONS OF APPROVAL, IF ANY:		

9/3 RIH w/tbg & tagged cmt plug @4395'. Pumped 20 sx Class "H" cmt plug @4395'. POOH w/20 stands tbg. SD for 4 hrs. RIH & tagged cmt plug @4238'. POOH w/tbg to 2120' & pumped 35 sxs Class "H" cmt plug from 2120-2004'. POOH w/tbg & spotted 10 sx cmt plug at surface. Cut off well head & weld on plate. Installed dry hole marker. Well plugged and abandoned 9/3/86.