

OIL CONSERVATION DIVISION

P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-73

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. LG 3726	

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT - II" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- P&A		7. Unit Agreement Name Sandsage State Unit
2. Name of Operator Yates Petroleum Corporation		8. Farm or Lease Name Sandsage State Unit
3. Address of Operator 105 South 4th St., Artesia, NM 88210		9. Well No. 1
4. Location of Well UNIT LETTER E 2310 FEET FROM THE North LINE AND 330 FEET FROM West LINE, SECTION 16 TOWNSHIP 15S RANGE 35E NMPM.		10. Field and Pool, or Wildcat Wildcat
15. Elevation (Show whether DF, RT, GR, etc.) 4019' GR		12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plugged well as follows:

Set CIBP at 11275' and capped w/10 sx cement. Circulated hole w/heavy mud.  
Cut and pulled 5 1/2" casing at 7484'.  
Spot 25 sx plug at 8200' across Abo top.  
Spot 25 sx plug at 7550'. Tagged plug at 7440'.  
Spot 25 sx plug at 5382' across Glorieta top.  
Spot 25 sx plug at 4700'. Tag at 4610' (plug across 8-5/8" casing shoe)  
Spot 25 sx plug at 1800' across top of Salt.  
Spot 10 sx surface plug.  
Cut off wellhead and set dry hole marker.

Completed plugging 1-8-87.

Plugging witnessed by Ray Smith, w/NMOCD, Hobbs, NM.

Verbal approval for plugging given by Mr. Eddie Seay, NMOCD, Hobbs, NM, on 10-30-86.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Juanita Goodlett</u>	TITLE <u>Production Supervisor</u>	DATE <u>1-12-87</u>
APPROVED BY <u>Lyle F. Turna Cliff</u>	TITLE <u>OIL &amp; GAS INSPECTOR</u>	DATE <u>DEC 29 1988</u>
CONDITIONS OF APPROVAL, IF ANY:		