

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 300252978000
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. B-11454
7. Lease Name or Unit Agreement Name WEST ANDERSON RANCH STATE
8. Well No. 1
9. Pool name or Wildcat W. ANDERSON RANCH WOLFCAMP

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	
2. Name of Operator ARCO OIL AND GAS COMPANY	
3. Address of Operator BOX 1710, HOBBS, NEW MEXICO 88240	
4. Well Location Unit Letter <u>E</u> : <u>1980</u> Feet From The <u>NORTH</u> Line and <u>660</u> Feet From The <u>WEST</u> Line Section <u>9</u> Township <u>16S</u> Range <u>32E</u> NMPM LEA County <u></u>	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) <u>4363.3 RKB</u>	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <u>Test Wolfcamp 9619-9628' unsuccessful</u> <input checked="" type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

6-06-89 N.D. W.H. to unset Pkr. N.U. BOP tallied out of hole.

6-07-89 Set R.B.P. @ 9776'. Loaded hole w/2% KCL & fresh, press. up to 500# on backside. Held press. POH w/tbg & on & off tool. R.U. Bell Surveys to perforate. Shot perfs 20 holes @ 9616' to 9628' 2 JSPF. R.D. Bell. RIH w/7" Model R Pkr & 304 Jts. 2-7/8" tbg. S.D.O.N.

6-08-89 RIH to perfs. Spotted 200 gal. acid & mix across perfs. POH to 9451', set Pkr & R.U. Halliburton to acidize perfs. Could not get formation to break ISIP 4100#, 15 min. later 4000#, 30 min. later 3900#. R.D. Halliburton. Unset Pkr & POH w/tbg & Pkr.

6-09-89 R.U. Bell Surveys to perforate. Shot perfs again. R.D. Bell. RIH w/7" Model R, 2-7/8" S.N., & tbg. R.U. Halliburton Services. Spotted 200 gal. acid mix across new perfs. Tried to break down perfs but was unable to do so. ISIP 4000#, 30 min. SIP 3800#. R.D. Halliburton & released. Unset Model R Pkr. RIH to 9776'. Unset R.B.P. POH w/tbg & Pkr & plug.

6-12-89 RIH w/profile nipple, M.A., 2-4' P.N.'s, S.N., & 317 Jts. 2-7/8" tbg. N.D. BOP N.U. W.H. R.A. & cleaned location.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE James D. Cogburn TITLE Services Supervisor DATE 6-27-89

TYPE OR PRINT NAME James D. Cogburn TELEPHONE NO. 392-3551

(This space for State Use) ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

JUN 29 1989