

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.

30-025-29787

5. Indicate Type of Lease

STATE ☐

FEE ☒

6. State Oil & Gas Lease No.

044198

7. Lease Name or Unit Agreement Name

J. BENSON

8. Well No.

1

9. Pool name or Wildcat

North Knowles-Devonian

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL
WELL ☒

GAS
WELL ☐

OTHER

2. Name of Operator

Marathon Oil Company

3. Address of Operator

P.O. Box 552 Midland, Tx. 79702

4. Well Location

Unit Letter P : 330 Feet From The South Line and 990 Feet From The East Line

Section 14

Township 16-S

Range 38-E

NMPM LEA

County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

GL: 3698

DF: 3722.4

KB: 3723.4

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

11/20/93 MIRU

12/1/93 Release Packer - Load hole w/10# Brine, POH w/tubing & remove packer- GIH w/tubing to 9700'.

12/2/93 Mix & pump 45 sx cement @ 9700', WOC 4 hrs. Tag plug @ 9494'. Pump 24 BBL Mud- Pull Tbg to 8381. Mix & pump 40 sx cement.

12/6/93 Tubing stuck - Cut tbg @ 6723' - Did not come.

12/7/93 Cut tbg @ 6718'. POH.

12/9/93 Cut 5½ csg. @ 6350'. POH w/csg.

12/13/93 Run tbg. to 6402 - Pump 140 sx cement. WOC.

12/14/93 Tag cement @ 6069. Pumped 130 BBL Mud.

12/15/93 Finish loading hole w/mud. Pull tbg. to 5070' - Pump 75 sx cement. WOC.

12/16/93 Tag plug @ 4865' - Pull tbg to 2605'. Pump 55 sx cement. Pull tbg to 376'. Pump 55 sx cement. Pull tbg to 60'. Pump 25 sx cement. Cap well. Install Dry Hole Marker. Clean location. Rig down. Move.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

TITLE Owner

DATE 1-20-94

TYPE OR PRINT NAME

Chris Ball, Ball Oilfield Service

TELEPHONE NO. 817-629-8563

(This space for State Use)

ORIGINAL SIGNED BY

GARY WINK

APPROVED BY

REP. II

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

JUL 17 1997