

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO.
30-025-29787

5. Indicate Type of Lease
STATE ☐ FEE ☒

6. State Oil & Gas Lease No.
044198

7. Lease Name or Unit Agreement Name
BENSON

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☒ GAS WELL ☐ OTHER

2. Name of Operator
Marathon Oil Company

8. Well No.
1

3. Address of Operator
P.O. Box 552 Midland, Tx. 79702

9. Pool name or Wildcat
NORTH KNOWLES-DEVONIAN

4. Well Location
Unit Letter P : 330 Feet From The SOUTH Line and 990 Feet From The EAST Line

Section 14 Township 16-S Range 38-E NMPM LEA County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

GL:3698 DF:3722.4 KB:3723.4

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

MARATHON OIL PROPOSES TO P&A THIS WELL USING THE PROCEDURE OUTLINED BELOW.
TEST ANCHORS. MIRUPU. SET CIBP @ 13,000'. DUMP 5 SX CMT ON TOP OF PLUG. LOAD HOLE WITH 10#/GALLON
BRINE WITH 25#/BBL GEL.
SET BALANCED PLUG 11240'-11340' + 50% EXCESS. TAG PLUG
SET BALANCED PLUG 9440-9540 + 50% EXCESS. TAG PLUG
SET BALANCED PLUG 8270-8370 + 50% EXCESS. TAG PLUG
CUT CASING @ 7200'. SET BALANCED PLUG 50' BOVE AND BELOW CUT OFF + 100% EXCESS. PULL CASING. TAG PLUG.
SET BALANCED PLUG 6277-6377 + 100% EXCESS. TAG PLUG
SET BALANCED PLUG 4070-5070 + 100% EXCESS. TAG PLUG
SET BALANCED PLUG 2500-2600 + 50% EXCESS. TAG PLUG
SET BALANCED PLUG 270-370 + 50% EXCESS. TAG PLUG
SET PLUG SURF TO 50'. CUT OFF CSG 3' BELOW GROUND LEVEL. INSTALL DRY HOLE MARKER. RDMO. CLEAN AND
LEVEL LOCATION

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE _____ TITLE ADVANCED ENG. TECH DATE 1-18-93
TYPE OR PRINT NAME THOMAS M. PRICE *Thomas M Price* TELEPHONE NO. 915-682-1626

(This space for State Use)

Orig. Signed by
Paul Kanta
Geologist

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

JAN 21 1993