

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
310 Old Santa Fe Trail, Room 206
Santa Fe, New Mexico 87503

WELL API NO.
30-025-29794

5. Indicate Type of Lease
STATE ☐ FEE ☒

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☒ GAS WELL ☐ OTHER

2. Name of Operator
Amerind Oil Company Limited Partnership

3. Address of Operator
415 W Wall Suite 500, Midland TX 79701

4. Well Location
Unit Letter K : 1980 Feet From The South Line and 2130 Feet From The West Line
Section 33 Township 16S Range 37E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
3782' GL

7. Lease Name or Unit Agreement Name

Meyers

8. Well No.
2

9. Pool name or Wildcat
Knowles Drinkard West

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1.) MIRU plugging equipment. POOH w/prod equipment. Set CIBP @ 7825' w/35' cmt (3 sx).
- 2.) Displace w/10#/gal brine + 25#/bbl gel. Freepoint & cut 4½" csg @ ± 6000'.
- 3.) POOH w/csg. TIH w/tbg. Set 50 sx cmt plug @ stub 50' inside/50' outside & tag.
- 4.) Set 50 sx out plug @ 4250', 50' inside/50' outside 8-5/8" shoe @ 4200' & tag.
- 5.) Set 60 sx cmt plug @ 2050'. Set 10 sx surf plug. Weld on dry hole marker.
- 6.) Remove equipment, restore loc.

Work to be performed ASAP.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE James E. Yeley TITLE Agent DATE 2/9/93
TYPE OR PRINT NAME Jim E. Yeley TELEPHONE NO. 915/682-8217

(This space for State Use)
ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

FEB 11 1993

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED
FEB 10 1993
OCD HOBBS OFFICE