

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-29817
5. Indicate Type of Lease	STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name	
Christmas	
8. Well No.	1
9. Pool name or Wildcat	NE. Lovington Wolfcamp

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	
2. Name of Operator	Bahlburg Exploration, Inc.
3. Address of Operator	14875 Landmark Blvd., Suite 216, Dallas, TX 75240
4. Well Location	Unit Letter D : 1200 Feet From The North Line and 600 Feet From The West Line Section 7 Township 16 S Range 37 E NMPM Lea County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3856.9 GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Proposed Plugging Procedure( Per Mr. Sexton 2/10/94)

Set CIBP @ 10,200 ft. w/ 35 ft. cement on top.  
Cut and pull 5-1/2" csg. @ approx. 7000 ft. Load hole with mud.  
Set 100' cement plug 50' in and out of 5-1/2" csg. stub. Tag plug.  
Set 100' cement plug 50' in and out of 8-5/8" csg. shoe.  
Set 35 sack cement plug at 1700 ft.  
Set 10 sack cement plug at surface and install surface marker.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE William C. Bahlburg TITLE President DATE 2/10/94  
TYPE OR PRINT NAME William C. Bahlburg TELEPHONE NO. 214/392-0123

(This space for State Use)

Orig. Signed by  
Paul Kantz  
Geologist

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY:

THIS COPIED TO BE NOTED BY  
THE OFFICE OF THE ATTORNEY GENERAL  
IN THE EVENT OF A LITIGATION  
TO BE FILED IN THE COURT OF THE STATE

FEB 10 1994

df