



105 SOUTH FOURTH STREET  
ARTESIA, NEW MEXICO 88210  
TELEPHONE (505) 748-1471

S. P. YATES  
PRESIDENT  
JOHN A. YATES  
VICE PRESIDENT  
B. W. HARPER  
SEC. - TREAS.

May 27, 1987

State of New Mexico  
Energy and Minerals Department  
Oil Conservation Division  
Hobbs District Office  
P. O. Box 1980  
Hobbs, New Mexico 88241-1980

ATTENTION: Mr. Jerry Sexton, Supervisor

Re: Brown AEI #1-H 26-16-37


Dear Mr. Sexton:

We have not filed a completion report on the above captioned well due to difficulty in producing the well. The wellbore is excessively crooked which has foiled our attempts to test the well. So far, we have broken five (5) swab lines, swab testing without results. The pumping unit installed has not been able to pump the well, again, due to the crooked hole. We, now, plan to test the well with an electric submergible pump.

For the above stated reasons, we request additional testing allowable for the well. We, also, request change of transporter effective June 1, 1987. Form C-104 is attached.

Thank you for your consideration in this matter.

Yours truly,

  
Juanita Goodlett  
Production Supervisor

Encl.