

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-30212

5. Indicate Type of Lease-
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name-

War State "30"

8. Well No. 1 =

9. Pool name or Wildcat
Wildcat

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. Name of Operator
Union Oil Company of California

3. Address of Operator
P. O. Box 671 - Midland, Texas 79702

4. Well Location
Unit Letter K : 1850 Feet From The west Line and 2310 Feet From The south Line

Section 30 Township 15-S Range 32-E NMPM Lea County

10. Elevation (Show whether DP, RKB, RT, GR, etc.)
4341.1' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS ☐ PLUG AND ABANDONMENT ☒
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

10-6: MI RU BABER WELL SERVICE. SDON.

10-7: INSTALL BOP. REL TAC, POOH W/2-7/8" TBG. RIH W/CIBP ON 2-7/8" TBG & SET CIBP @ 9727'. DISPLACE HOLE W/10# MUD. SPOT 10 SXS CMT @ 9727-9630'. POOH TO 7000', INCOMP. SDON.

10-8: POOH W/2-7/8" TBG. ND BOP & TBG HD. WELD ON PULL NIPPLE. SDON.

10-9: FREE PT 5-1/2" CSG @ 7000'. CUT 5-1/2" CSG @ 7000' W/JET CUTTER. PULL OUT & LAY DN 5-1/2" CSG, INCOMP. SDON.

10-10: SDOS.

10-11: FINISH LAYING DN 5-1/2" CSG. TOTAL 173 JTS & 2 PCS (6963'). INSTALL BOP. RIH W/2-7/8" TBG TO 7052'. LOADED HOLE W/10 PPG MUD. SPOT 70 SXS CMT FROM 7052-6780'. POOH, INCOMP. SDON.

10-12: RIH W/2-7/8" TBG & TAG CMT. PLUG @ 6930'. PU & SPOT 25 SXS CMT FROM 5800-5700'. POOH. RIH W/CIBP ON 2-7/8" TBG & SET @ 4002'. SPOT 30 SXS CMT FROM 4000-3900'. PU TO 1250'. SPOT 25 SXS CMT FROM 1250-1150'. PU TO 500'. SPOT 25 SXS CMT FROM 500-400'. POOH, ND BOP & WELL HD. SPOT 10 SXS CMT FROM 30' TO SURFACE.

10-13: CUT OFF WELL HDS, WELD ON P&A PLATE. INSTALL DRY HOLE MARKER. CLEAN LOCATION. RIG DN PUL WELL P&A'S 10-12-88.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Jeffery J. Tokarsky TITLE Drilling Engineer DATE 1-20-89

TYPE OR PRINT NAME Jeffery J. Tokarsky

TELEPHONE NO. 915 682-9731

(This space for State Use)

APPROVED BY [Signature] TITLE OIL & GAS INSPECTOR DATE 00T 16 1991

CONDITIONS OF APPROVAL, IF ANY: