

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

**OIL CONSERVATION DIVISION**  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

|                                                                                                     |
|-----------------------------------------------------------------------------------------------------|
| WELL API NO.<br>30-025-30259                                                                        |
| 5. Indicate Type of Lease<br>STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/> |
| 6. State Oil & Gas Lease No.<br>L990                                                                |

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

|                                                                                                                                   |                                                  |
|-----------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------|
| 1. Type of Well:<br>OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/> | 7. Lease Name or Unit Agreement Name<br>State 35 |
| 2. Name of Operator<br>PG&E Resources Company                                                                                     | 8. Well No.<br>1                                 |
| 3. Address of Operator<br>6688 N. Central Expwy., Suite 1000, Dallas, TX 75206                                                    | 9. Pool name or Wildcat<br>Shipp Strawn          |
| 4. Well Location<br>Unit Letter <u>P</u> <u>600</u> Feet From The <u>South</u> Line and <u>660</u> Feet From The <u>East</u> Line |                                                  |

Section 35 Township 16S Range 37E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

3753.9' KB

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

**NOTICE OF INTENTION TO:**

|                                                |                                           |
|------------------------------------------------|-------------------------------------------|
| PERFORM REMEDIAL WORK <input type="checkbox"/> | PLUG AND ABANDON <input type="checkbox"/> |
| TEMPORARILY ABANDON <input type="checkbox"/>   | CHANGE PLANS <input type="checkbox"/>     |
| PULL OR ALTER CASING <input type="checkbox"/>  |                                           |
| OTHER: <input type="checkbox"/>                |                                           |

**SUBSEQUENT REPORT OF:**

|                                                     |                                                          |
|-----------------------------------------------------|----------------------------------------------------------|
| REMEDIAL WORK <input type="checkbox"/>              | ALTERING CASING <input type="checkbox"/>                 |
| COMMENCE DRILLING OPNS. <input type="checkbox"/>    | PLUG AND ABANDONMENT <input checked="" type="checkbox"/> |
| CASING TEST AND CEMENT JOB <input type="checkbox"/> |                                                          |
| OTHER: <input type="checkbox"/>                     |                                                          |

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

6/11/93 RIH w/pkr & set @8200'. Mix & pump 200sx cmt plug. POOH & LD pkr. RIH to 6200'. Set 100sx cmt plug (800') pull up to 4000'.

6/14/93 Tag cmt @6200'. POOH w/tbg. RIH w/perf gun & perf @4515'. POOH. RIH w/cmt retainer & set @4450'. Pump 50sx cmt below retainer & leave 10sx on top. Pull up to 2150' & pump 12sx. Balance cmt plug & pull up to 1630'. Pump 60sx in 8-5/8" x 5-1/2". Leave 20sx in 5-1/2".

6/15/93 RIH & tag cmt plug @1630'. Pump 100sx @1630' to plug csg leak per Oil Conservation Representative. RIH & tag cmt @1630'. Pump in 80sx cmt w/cottonseed hulls.

6/18/93 RIH & tag cmt @1505'. Pull up hole & set 25sx cmt plug at surface. POOH & cut off csg 3' below ground level. Well P&A.

6/21/93 PU flow lines & restore location for Oil Conservation approval.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Cindy Keister TITLE Regulatory Analyst DATE 07/20/93

TYPE OR PRINT NAME

TELEPHONE NO. (214) 750-3800

(This space for State Use)

APPROVED BY Cathy W. Hill TITLE OIL & GAS INSPECTOR DATE NOV 23 1993

CONDITIONS OF APPROVAL, IF ANY:

SAO

**RECEIVED**

APR 17 1993

ODD HOUSE  
OFFICE