State of New Mexico Energy, minerals and Natural Resources Department

Form C-103 Revised 1-1-89

District Office	
P.O. Box 1980, Hobbs, NM \$8240 OIL CONSERVATION DIVISION 310 Old Santa Fe Trail, Room 206 30-025-30353	
DISTRICT II P.O. Drawer DD, Artesia, NM 88210 Santa Fe, New Mex	100 87303 5. Indicate Type of Lease
DISTRICT III 1000 Rio Brazos Rd., Aziec, NM 87410	6. State Oil & Gas Lesse No.
<u></u>	
SUNDRY NOTICES AND REPORTS ON WE (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN	LOD DILLO BACKTOA
DIFFERENT RESERVOIR. USE "APPLICATION FOR PE (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well:	
OIL ONS WELL Dry	Rouse 5
2. Name of Operator Chesapeake Operating, Inc.	8. Well No.
3. Address of Operator	9. Pool name or Wildcat
P. O. Box 18496, Okla. City, OK 73154-0496	West Lovington Strawn
Unit Letter : 3950 Feet From The N Line and 1537 Feet From The W Line	
Section 5 Township 16S	ange 36E NMPM LEA County
//////////////////////////////////////	r DF, RKB, RT, GR, etc.)
GR: 394	
NOTICE OF INTENTION TO:	Nature of Notice, Report, or Other Data SUBSEQUENT REPORT OF:
NOTICE OF INTENTION TO.	
PERFORM REMEDIAL WORK PLUG AND ABANDON PLUG AND ABANDON	REMEDIAL WORK ALTERING CASING
TEMPORARILY ABANDON CHANGE PLANS	COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT X
PULL OR ALTER CASING	CASING TEST AND CEMENT JOB
OTHER:	OTHER: Rig Release X
12. Describe Proposed or Completed Operations (Clearly state all pertinent details,	and give pertinent dates, including estimated date of starting any proposed
work) SEE RULE 1103. 06/16/00 RD logging crew, TIH w/DCs, change swivels, LD DCs & jars, TIH, pull 23 jts DP	
out of basket PN same, break circ, pump plug #1, 28 sx Cl. H @ 11750-11650',	
pull 21 stds DP + single, pump plug #2, 28 sx C1. H 15.6 PPG, 1.17 yield,	
@9720-9120', pull 23 stds DP, pump plug #3, 28 sx Cl. H @7550-7450', pull 6 stds, but LD 19 jts DP, pump Plug #4, 28 sx @ 6400-6300', LD 52 jts, pump Plug #5, 35 sx	
Cl. H @ 4750-4584, LD 150 its DP, TIH 40 stds, circ, TIH, tag cmt @ 4584',	
set 15,000# on cmt, LD 87 jts DP, break kelly, pump Plug #6, 28 sx @1950-1850', LD 50 jt DP, LD 50 jts, pump Plug #7 w/28 sx C1. H w/2% Ca1 425'-325', LD kelly	
LD 50 jt DP, LD 50 jts, pump Plug #	7 w/28 sx C1. H w/2% Cal 425 -325, LD Relly, TIH, tag cmt @ 188', LD 12 jts DP, PU 2",
nump 75' cmt to surface, weld marke	r on 8-5/8", clean pit, set out front end,
release Patterson. Drilling Rig #48 @ 6 p.m. Well P&A'd	
I hereby certify that the information above is true and complete to the best of my knowledge and	pelief.
SIGNATURE Sarbara J Bale	Regulatory Analyst DATE 06/26/00
TYPEOR PRINT NAME Barbara J. Bale	TELEPHONE NO. (405) 848-8000
(Thus space for State Use) / .	
Kill S L. O)	
APPROVED BY BULLY C. Truline.	TITLE DATE

GWW

