

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. L-6721
7. Lease Name or Unit Agreement Name STATE 8
8. Well No. 2
9. Pool name or Wildcat HUME, NORTH WOLFCAMP
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3134 GL 4150 KB

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator W. A. MONCRIEF, JR.
3. Address of Operator MONCRIEF BUILDING, NINTH @ COMMERCE, FORT WORTH, TX	4. Well Location Unit Letter <u>B</u> : <u>660</u> Feet From The <u>FNL</u> Line and <u>1980</u> Feet From The <u>FEL</u> Line Section <u>8</u> Township <u>16S</u> Range <u>34E</u> NMPM <u>LEA</u> County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

4-15-89 Spot 25 sx cmt w/2% CaCl @ 9900' WOC 4 hrs. WIH didn't tag cmt. spot 25 sx cmt. w/2% CaCl
4-16-89 Tag cmt at 9837'. Load hole w/10# brine w/25# gel bbl.
4-18-89 Cut 5 1/2" csg off at 8007'.
4-19-89 FOOH w/ 5 1/2" csg. WIH w/tbg to 4788', hit bridge.
4-20-89 TIH w/mill. Mill wore on sides.
4-21-89 TIH w/tbg to bridge to 4788', spot 35 sx cmt w/2% CaCl. WIH did not tag cmt. spot 2nd 35 sx cmt plug @ 4788'.
4-22-89 TIH tag cmt at 4721' pull to 50' below 8 5/8" spot 50 sx cmt w/2% CaCl. WOC 4 hrs TIH tag cmt at 4274'. plug ok. Pull up to 1572' spot 35 sx cmt. POOH. Cut wellhead. Place 10 sx cmt at surface, install dry hole marker.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Patsy Salcomb TITLE AGENT DATE 5-29-91
TYPE OR PRINT NAME _____ TELEPHONE NO. _____

(This space for State Use)

APPROVED BY Lyle F. Turnacliff TITLE Oil & Gas Division DATE JUN 4 1991
CONDITIONS OF APPROVAL, IF ANY:

Photo PA 6/3/91 BP