

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
30-025-30433

5. Indicate Type of Lease
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. Name of Operator
AMERIND OIL CO. *L.P.*

3. Address of Operator
500 WILCO BLDG., MIDLAND, TX 79702

4. Well Location
Unit Letter **C** : **1980** Feet From The **West** Line and **510** Feet From The **North** Line

Section **32** Township **16S** Range **37E** NMPM LEA County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. MOVE IN AND RIG UP. POOH AND LAY DOWN RODS & PUMP.
2. INSTALL BOP. POOH W/ TBG.
3. SET CIBP @ $\pm 11,100'$. CAP W/ 35' OF CEMENT. LOAD HOLE W/ 10# SALT GEL.
4. SET 100' CEMENT PLUG @ 9500'.
5. SET 100' CEMENT PLUG @ 5 1/2" CASING STUB $\pm 8000'$ - 50' IN & OUT. TAG.
6. SET 100' CEMENT PLUG @ 6090'. (GLORIETA)
7. SET 100' CEMENT PLUG @ 4270'. (8 5/8" SHOE - SAN ANDRES) *Ray*
8. SET 100' CEMENT PLUG @ 2145'. (TOP OF SALT)
9. SET 10 SK. SURFACE PLUG. CUT OFF WELLHEAD. INSTALL DRY HOLE MARKER. RIG DOWN & CLEAN LOCATION.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

GUY A. BABER

TITLE

PRESIDENT - BABER WELL SERV. DATE 6-1-90

TYPE OR PRINT NAME

TELEPHONE NO. 505-393-5516

(This space for State Use)

Orig. Signed by
Paul Kautz
Geologist

APPROVED BY

TITLE

DATE

JUN 04 1990

CONDITIONS OF APPROVAL, IF ANY: