Submit 3 Copies to Appropriate District Office

State of New Mexico Energy, Minerals and Natural Resources Department

Form (C-103	
Revised	11.1-8	9

DISTRICT I P.O. Box 1980, Hobbs, NM 88240	1 1980 Hobbs NM 88240		WELL API NO.			
	P.O. Box 2088 Santa Fe, New Mexico 87504-2088		30-025-30564			
DISTRICT II P.O. Drawer DD, Artesia, NM 88210			5. Indicate Type of Lease			
DISTRICT III			STATE	FEE		
1000 Rio Brazos Rd., Aztec, NM 87410			6. State Oil & Gas Lease No. LG-6393			
SUNDRY NOTI	CES AND REPORTS ON WE	LLS				
(DO NOT USE THIS FORM FOR PRO	POSALS TO DRILL OR TO DEEPER	N OR PLUG BACK TO A	7. Lease Name or Unit Agreement	//////////////////////////////////////		
	IVOIR. USE "APPLICATION FOR PE 101) FOR SUCH PROPOSALS.)	:RMIT				
1. Type of Well:						
MET X CAS MET C	OTHER		East Lovington 17 S	State		
2. Name of Operator			8. Well No.			
Harvey E. Yates Com 3. Address of Operator	pany		#2			
1	well, New Mexico 8820	12	9. Pool name or Wildcat			
4. Well Location	Well's New Hexteo 8020	<u> </u>	N.E. Lovington Penn	<u></u>		
Unit Letter F : 1980	Feet From The North	Line and13	70 Feet From The Wes	t Line		
Section 17	- 16C	275				
Section 1/	Township 16S R 10. Elevation (Show whether	ange 37E	NMPM Le	d County		
	//////	345.2 GL				
11. Check A	Appropriate Box to Indicate		eport, or Other Data			
NOTICE OF INTENTION TO: SUBSEQUENT				= ;		
PERFORM REMEDIAL WORK PLUG AND ABANDON X REMEDIAL WORK			ALTERING CAS	SING		
PULL OR ALTER CASING	COMMENCE DRILLING		ANDONMENT L			
		CASING TEST AND CE	MENT JOB			
OTHER:	U	OTHER:				
 Describe Proposed or Completed Operation Work) SEE RULE 1103. 	ons (Clearly state all pertinent details, a	nd give pertinent dates, includ	ling estimated date of starting any prop	posed		
* Fxisting Perfs 0	11376-406, TOC @ 108	າດດ '				
1) POOH w/tbg & pkr	11070 400, 100 6 100	,00				
2) Set CIBP @ 11350	w/35' of cement on to					
3) Shoot off 5 1/2" csg @ 10702, Pull csg 00H						
4) Set 100' plug in	& out of 5 1/2" csg	·02 \				
5) Set 100' plug in & out of Wolfcamp (9723)						
6) Set 100' plug in & out of Glorietta (6531) 7) Set 100' plug in & out of San Andres (5058)						
8) Set 100' plug in	& out of 8 5/8 shoe (4470)				
9) Set 100' plug in	& out of Rustler (213	1)				
10) Set 10 skplug on	surface w/marker					
I hereby certify that the information above is true :	and complete to the best of my knowledge and	beliaf.				
AMIlye		Drlg Superinte	endent 5/2	3/89		
SIGNATURE NM Young	TIT	LE				
TITE OK FRINT NAME	TELEPHONE NO	. 623-6601				
Phil mai hi this Upi ORIGINAL SIGNET	BY JERRY SEXTON		MAY	2 5 1988		
	SUPERVISOR TITLE		(***	N U IUUU		
CONDITIONS OF APPROVAL, IF ANY:	IIII		DATE			

THE COMMISSION MUST BE NOTIFIED 24 HOURS FROM TO THE BEGINNING OF SUCCEMO OFFICATIONS FOR THE C-103 TO BE AFTROYED.