## State of New Mexico Thergy, Minerals and Natural Resources Departm

Form C-103 Revised 1-1-89

DISTRICT I

OI

L CONSERVATION DIVISION	WELL API NO.			
P.O. Box 2088	30-025-30598			
Santa Fe, New Mexico 87504-2088	5. Indicate Type of Lease			

P.O. Box 1980, How	P.O. Box 1980, Hobbe, NM 88240 P.O. Box 2088		20 025 2	0500				
DISTRICT II P.O. Drawer DD, Artesia, NM \$8210  Santa Fe, New Mexico 87504-2088		30-025-30598  5. Indicate Type of Lease						
		J. Indicate Lyps	STATE	FEE 🗌				
DISTRICT III 1000 Rio Brazos Rd., Aziec, NM 87410		6. State Oil & C						
	SUNDRY	NOTIC	ES AND REPORTS O	N WE	LLS			
( DO NOT USE TI	HIS FORM FO DIFFERENT I	XR PROP RESERV	OSALS TO DRILL OR TO D OIR. USE "APPLICATION F OI) FOR SUCH PROPOSAL	EEPEN FOR PE	OR PLUG BACK TO A	7. Lease Name	or Unit Agreement Na	me
1. Type of Well:	<u>`</u>	<u>. X</u>	OTHER			Clydesd	ale 15 State	e
2. Name of Operato		<u> </u>	UITEX			8. Well No.		
Santa Fe	Energy (	Operat	ing Partners, L.	Ρ		1		<del></del>
3. Address of Open		044.	EOO Wallend T	· 70	0701		Wildcat Wildcar ovington Ato	
4. Well Location			500, Midland, T	A /:				
			Feet From TheEast	: 	Line and2300	Feet Fro	on The South	Line
Section	15		Township 16S	R	inge 36E 1	NMPM Lea	l	County
			10. Elevation (Show 3881.4'		DF, RKB, RT, GR, etc.)			
11.	Ch	eck Ap	propriate Box to Ind	icate l	Nature of Notice, Re	port, or Othe	r Data	
· NO	OTICE OF	INTE	NTION TO:		SUB	SEQUENT	REPORT OF:	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING			1G [					
TEMPORARILY ABA	MDON		CHANGE PLANS		COMMENCE DRILLING	OPNS.	PLUG AND ABAN	IDONMENT X
PULL OR ALTER CA	PULL OR ALTER CASING CASING TEST AND CEMENT JOB							
OTHER:					OTHER:		•	
12. Describe Propose work) SEE RUL	E 1103.		ns (Clearly state all pertinent d					
8-14-89:	Notifie orders	d NMO	CD in Hobbs, NM, District I.	of i	ntent to plug &	abandon.	Received pl	ugging
8-15-89:	3 3 3	5 sx 5 sx 5 sx	Trip in hole ope 11,540-11,440' 9,602- 9,502' 8,312- 8,212'	3 5 3	35 sx 6,331-6,5 60 sx 4,860-4, 35 sx 2,200-2,	231' 710' 100'		
8-16-89:	Set sur head &	face set d	plug. Lay down o ry hole marker.	irill Rele	pipe. Strip ce eased rig at 1:3	llar. Cut O PM on 8-1	off 8 5/8" 16-89. Well	P&A'd.
		_						
I hereby certify that the	information abov	re is true and	t complete to the best of my knowl				0 2	1 00
SIGNATURE	ryy V	clu	lough	<u> </u>	Sr. Production	n Clerk	DATE	915/
TYPE OR FRINT NAME	Terry	McCul	lough				TELEPHONE NO.	687-3551
(This space for State U								
(Time share for some of		v//	·W		.* ,		•	
APTROVED BY	wy W	·Kfe	<i>v</i>	— m	u <u> </u>		DATE	<del></del>

CONDITIONS OF APPROVAL, IF ANY: