

MARTIN YATES, III
1912 - 1985
FRANK W. YATES
1936 - 1986



105 SOUTH FOURTH STREET
ARTESIA, NEW MEXICO 88210
TELEPHONE (505) 748-1471

S. P. YATES
CHAIRMAN OF THE BOARD
JOHN A. YATES
PRESIDENT
PEYTON YATES
EXECUTIVE VICE PRESIDENT
RANDY G. PATTERSON
SECRETARY
DENNIS G. KINSEY
TREASURER

DRILL STEM TESTS

DAISY AFS STATE #1 - VB-0015
2310' FNL & 1650' FEL, Sec. 3-T16S-R35E
Lea County, NM

DST #1 10200-10259' (59') WOLFCAMP: TIMES: 37", 60", 60", 180", 60".
SAMPLER: .25 cfg, 700 cc oil, 850 cc mud. RECOVERY: 465' oil/gas cut
mud. PRESSURES: IHP 4647, IFP 103-128, ISIP 1923, 2nd FP 153-379, 2nd
SI 2438, FFP 204-254, FHP 4672.

DST #2 11000-11059' (59'): TIMES: 30", 60", 60", 120", 50". RECOVERY:
drill pipe - trace oil on top, 2364' (29 bbls) gas cut mud, 50 Cl. 612'
(3 bbls) water cushion. SAMPLER: 2400 cc mud, 460 psig, 76000 Cl.
PRESSURES: IHP 5330, IFP 329-340, ISIP 5268, 2nd FP 338-336, 2nd SI 5267,
FFP 290-365; FHP 5330.

DST #3 11429-11500' (71') STRAWN: TIMES: 30", 60", 60". SAMPLER: .96
cfg, 1650 cc mud, 450 psig. RECOVERY: 1300' water cushion. PRESSURES:
IHP 5734, IFP 796-796, ISIP 2043, FFP 809-809, FHP 5734.