

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLI
(Other instructions on re-
verse side)

Form approved
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT..." for such proposals.)

RECEIVED
11 26 AM '90
CARLSBAD PERFORCE
AREA HEADQUARTERS

5. LEASE DESIGNATION AND SERIAL NO.

LC029410B

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

UNIT AGREEMENT NAME

7. FARM OR LEASE NAME

Federal AJ

8. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Maljamar GBSA

11. SEC., T., S., M., OR BLK. AND
SUBDIVISION OR AREA

Sec 31 T17S R32E

12. COUNTY OR PARISH

Lea

13. STATE

NM

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

OXY USA Inc.

3. ADDRESS OF OPERATOR

P.O. Box 50250 Midland, TX. 79710

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

1980 FNL 1980 FWL Sec 31 (SENW) T17S R32E

14. PERMIT NO.

300253079400S01

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3862.6'

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other) ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETION ☐

ABANDON* ☒

CHANGE PLANT ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) ☐

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

TD-4250' PBTD-3981' Perfs-3951'-3975'. It is proposed to Plug & Abandon in the following manner:

1. TOOH w/ tbg.
2. RU wireline, RIH w/ CIBP and set @ 3900'. RU dump bailer and dump 4 sx (50') on top of CIBP. RD wireline.
3. TIH w/ 2-7/8" tbg. circ hole w/ 9.5# mud laden fluid. Spot 10 sx plug from 3750'-3650'. Spot 10 sx plug from 3287'-3187'. Spot 10 sx plug from 2136'-2036'. Spot 34 sx plug from 1085'-750'. Spot 6 sx plug from 60'-surface.
4. TOOH & LD tbg, NDBOP, cutoff wellhead, install dry hole marker, RDP, cutoff anchors.

18. I hereby certify that the foregoing is true and correct

SIGNED

D. Charles Zhan

TITLE Supervisor - Prod. Rpt.

DATE 5/14/90

(This space for Federal or State office use)

(Prepared by David Stewart)

APPROVED BY

Orig. Signed by: *David Stewart*

TITLE

PERMITTEE

DATE

5-30-90

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side