

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy - Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-31114
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. V-1767
7. Lease Name or Unit Agreement Name West Sombrero State Unit
8. Well No. 1
9. Pool name or Wildcat West Hume Queen

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER PLUG & ABANDON
2. Name of Operator YATES PETROLEUM CORPORATION
3. Address of Operator 105 South 4th St., Artesia, NM 88210
4. Well Location Unit Letter J : 1980 Feet From The South Line and 1980 Feet From The East Line Section 16 Township 16S Range 33E NMPM Lea County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4228' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

8-15-95 - Moved in and rigged up pulling unit. POOH with rods and pump. NOTE: Notified Bonnie w/OCD-Hobbs of commencing plugging operations.
8-16-95 - Nippled up BOP. POOH with tubing, seating nipple, perforated sub and mud anchor. Rigged up wireline. TIH w/8-5/8" CIBP and set at 3850'. Rigged down wireline. TIH with tubing and tagged CIBP at 3850'. Spotted 230 bbls of plug mud from 3850' to surface. Mixed and pumped 35 sacks Class C cement from 3850-3750' (in 8-5/8" casing). POOH with tubing to 1533'. Mixed and pumped 35 sacks Class C cement from 1533-1433' (in 8-5/8" casing). POOH with 2-7/8" tubing to 478'. Mixed and pumped 35 sacks Class C cement from 478-378' in 8-5/8" casing. POOH with tubing to 50'. Mixed and pumped 15 sacks Class C cement from 50' to surface. POOH with tubing. Nippled down BOP. Rigged down pulling unit. Cleaned location and installed regulation abandonment marker. PLUGGED AND ABANDONED
- FINAL REPORT. Plugging completed 8-14-95.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Rusty Klein TITLE Production Clerk DATE Aug. 18, 1995
TYPE OR PRINT NAME Rusty Klein TELEPHONE NO. 505/748-1471

(This space for State Use)

APPROVED BY Larry W. Sill TITLE OIL & GAS INSPECTOR DATE Nov 16 1995
CONDITIONS OF APPROVAL IF ANY:

RECEIVED

AUG 21 1980

OLD HOBBS
OFFICE