

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Mines and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

**OIL CONSERVATION DIVISION**  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

|   |
|---|
| WELL API NO.<br>30-025-31114  |
| 5. Indicate Type of Lease<br>STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/> |
| 6. State Oil & Gas Lease No.<br>V-1767  |
| 7. Lease Name or Unit Agreement Name<br>West Sombrero State Unit                                    |
| 8. Well No.<br>1  |
| 9. Pool name or Wildcat<br>West Hume Queen  |
| 10. Elevation (Show whether DF, RKB, RT, GR, etc.)<br>4228' GR                                      |

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

|   |   |
|---|---|
| 1. Type of Well:<br>OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/> | 2. Name of Operator<br>YATES PETROLEUM CORPORATION  |
| 3. Address of Operator<br>105 South 4th St., Artesia, NM 88210  | 4. Well Location<br>Unit Letter J : 1980 Feet From The South Line and 1980 Feet From The East Line<br>Section 16 Township 16S Range 33E NMPM Lea County |
| 10. Elevation (Show whether DF, RKB, RT, GR, etc.)<br>4228' GR  |   |

|   |   |
|---|---|
| 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data |   |
| <b>NOTICE OF INTENTION TO:</b>  | <b>SUBSEQUENT REPORT OF:</b>                        |
| PERFORM REMEDIAL WORK <input type="checkbox"/>                                | REMEDIAL WORK <input type="checkbox"/>              |
| TEMPORARILY ABANDON <input type="checkbox"/>                                  | ALTERING CASING <input type="checkbox"/>            |
| PULL OR ALTER CASING <input type="checkbox"/>                                 | COMMENCE DRILLING OPNS. <input type="checkbox"/>    |
| OTHER: <input type="checkbox"/>   | PLUG AND ABANDONMENT <input type="checkbox"/>       |
|   | CASING TEST AND CEMENT JOB <input type="checkbox"/> |
|   | OTHER: <input type="checkbox"/>                     |

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to plug and abandon well as follows:

1. Set CIBP at 3850' and cap with 35' of cement.
2. Spot a 100' (25 sack minimum) cement plug across the top of the Rustler at 1483'.
3. Spot a 100' (25 sack minimum) cement plug across the 13-3/8" casing shoe at 428'.
4. Spot a 10 sack cement plug at surface.
5. Install regulation abandonment marker.

NOTIFY OCD-HOBBS (505-393-6161) 24 HOURS PRIOR TO COMMENCING PLUGGING OPERATIONS

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Rusty Klein TITLE Production Clerk DATE July 12, 1995  
TYPE OR PRINT NAME Rusty Klein TELEPHONE NO. 505/748-1471

(This space for State Use) **ORIGINAL SIGNED BY JERRY SEXTON**  
DISTRICT I SUPERVISOR

APPROVED BY \_\_\_\_\_

TITLE \_\_\_\_\_

DATE

**JUL 17 1995**

CONDITIONS OF APPROVAL, IF ANY:

Not  
P-ated up  
JP

f

RECEIVED

JUL 13 1986

U.S. DEPT. OF JUSTICE

CRIMINAL