

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-31229
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. V-2032
7. Lease Name or Unit Agreement Name Hondo State
8. Well No. #1
9. Pool name or Wildcat Seaman Penn North
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4,248' GR

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator Hondo Drilling Company
3. Address of Operator P.O. Drawer 2516 Midland, TX 79702-2516

4. Well Location Unit Letter <u>0</u> : <u>810'</u> Feet From The <u>South</u> Line and <u>1,980'</u> Feet From The <u>East</u> Line Section <u>18</u> Township <u>16S</u> Range <u>33E</u> NMPM Lea County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK <input checked="" type="checkbox"/> PLUG AND ABANDON <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER: <input type="checkbox"/>	SUBSEQUENT REPORT OF: REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/> CASING TEST AND CEMENT JOB <input type="checkbox"/> OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.
(estimated dates)
9-15-92 Set Halliburton bridge plug at 10,350'. Dump four sacks of cement with Dump Bailor. Plug back depth 10,310'
9-16-92 Perforate Wolfcamp Zone, 10,226' to 10,234'-two shots per ft. Total of 16 holes. Run 2 3/8" tubing and Guiberson Packer in hole, set same at 10,170'. Swabbing and testing well.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Nathan W. Outlaw TITLE President DATE 9/1/92
TYPE OR PRINT NAME Nathan W. Outlaw TELEPHONE NO. (915) 682-940

(This space for State Use)
ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE SEP 09 '92

CONDITIONS OF APPROVAL, IF ANY: