Submit 3 Copies to Appropriate District Office	Form C-103 Ent Revised 1-1-89
DISTRICT I OIL CONSERVATION DIVISIO	N WELL API NO.
P.O. Box 1980, Hobbs, NM 88240 P.O. Box 2088	30-025-31848
DISTRICT II Santa Fe, New Mexico 87504-2088 P.O. Drawer DD, Artesia, NM 88210	5. Indicate Type of Lease
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410	6. State Oil & Gas Lease No.
	V-2999
SUNDRY NOTICES AND REPORTS ON WELLS ( DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO DIFFERENT RESERVOR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OL GAS WELL X WELL OTHER	North Feather State Unit
2. Name of Operator	8. Well No.
H. L. Brown, Jr.	9. Pool name or Wildcat
3. Address of Operator P. O. Box 2237, Midland, TX 79702	Feather Morrow
4. Well Location	· · ·
Unit Letter <u>H</u> : <u>1650</u> Feet From The <u>North</u> Line and	990 Feet From The East Line
Section 16 Township 15-South Range 32-East NMPM Lea County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4297.9 GL	
II.       Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data         NOTICE OF INTENTION TO:       SUBSEQUENT REPORT OF:         PERFORM REMEDIAL WORK       PLUG AND ABANDON       REMEDIAL WORK       ALTERING CASING         TEMPORARILY ABANDON       CHANGE PLANS       COMMENCE DRILLING OPNS.       PLUG AND ABANDONMENT	
PULL OR ALTER CASING	
	······
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, work) SEE RULE 1103.	, including estimated date of starting any proposed
3/14/93 Reached TD of 12,480' @ 10:30 a.m. MST. 3/16/93 Reached TD of 12,480' @ 10:30 a.m. MST. 3/16/93 Reached TD of 12,480' @ 10:30 a.m. MST. 5½", 17#/ft BT&C and 2 jts, 209 jts, 5½", 5½", 17#/ft BT&C and 2 jts, 20#/ft BT&C casing at 12,479'. Cemented with a Lead Slurry of 45 + 2#/sx Hi-Seal. Tailed in w/900 sx Class H + 0.3% WR-15 + 0.35% Thrifty Lite + 2#/sx Hi-Seat 17:45 MST 3/16/93. Set slips on casing with Final pump pressure of 2300 psi. Tested plugs pressure. Plugs held OK. Released rig at 21:	g and set the shoe 50 sx PSL(H) + 0.6% CF-14 + 8#/sx CSE, 0.75% CF-14 Seal. Bumped plug th 200,000 lbs tension. s to 2800 psi. Then released
I hereby certify that the information above is true and complete to the best of my knowledge and belief. SKONATURE	on Engineer DATE <u>3/17/93</u> TELEPHONE NO. 915/683-5216
(This space for State Use) ORIGINAL SIGNAL BY JERRY CRATCH	MAR 2 2 1993
APPROVED BY TITLE	DATE DATE
CONDITIONS OF APPROVAL, IF ANY:	

## OCD HOBBS ATTEN

MAR 1 9 1993

......

RECEIVED