

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-31923
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No. NA
7. Lease Name or Unit Agreement Name CRESCENT --3--
8. Well No. 1
9. Pool name or Wildcat E. MORTON (Wolfcamp)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER
2. Name of Operator GECKO, Inc.
3. Address of Operator 310 W. Wall, Suite 702-LB106 Midland, Texas 79701
4. Well Location Unit Letter <u>E</u> : <u>991</u> Feet From The <u>WEST</u> Line and <u>1996</u> Feet From The <u>North</u> Line Section <u>3</u> Township <u>15S</u> Range <u>35E</u> NMPM <u>LEA</u> County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4000' GL

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

PROPOSED PROCEDURE

1. 100' cement plug at 10,700'
2. 100' cement plug at 7,400'
3. 100' cement plug at 6,135'
4. Cut 5 1/2" casing at 4,800' and pull. Set 100' cement plug from 4,750 - 4,650' (50' into and 50' out of 8 5/8" casing shoe).
5. 100' cement plug at 2,000'.
6. Cut 8 5/8" casing at 1,800' and pull. Set 100' cement plug from 490' - 390' (50' into and 50' out of 13 3/8" casing shoe).
7. 10 sxs cement surface plug.

ALL OPERATIONS MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS FOR THE C-103 TO BE APPROVED.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Steve L. Thomson TITLE President DATE 2/8/94
(915)
TYPE OR PRINT NAME Steve L. Thomson TELEPHONE NO. 686-0121

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON

APPROVED BY DISTRICT I SUPERVISOR TITLE DATE FEB 10 1994

CONDITIONS OF APPROVAL, IF ANY: