Submit 3 Copies to Appropriate District Office

State of New Mexico Energy, Manerals and Natural Resources Department

Form C-103 Revised 1-1-89

CONDITIONS OF APPROVAL, IF ANY:

P.O. Box 2088 Santa Fe, New Mexico 87504-2088 Santa Fe, New Mexico 87504-2088 S. Indicate Type of Loser STATE FE S. Sanc Oil & Gas Lose No. SUNDRY NOTICES AND REPORTS ON WELLS (OO NOT USE THIS FORM 700 PROPOSSALS) (OO NOT USE THIS FORM 700 PROPOSSALS) DEFERENCE OIL COMPANY The Wilser Oil Company S. Wall ON The Wilser Oil Company S. Wall ON The Wilser Oil Company S. Wall ON The Wilser Oil Company S. Wall No. B. Well No. B. Pool same or Wildest Mexical Grayburg San Andres Western The Wiser Line Western The Wiser Line Section Township 175 Sange 315 NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS OTHER: OTHER: SUBSEQUENT REPORT OF: REMEDIAL WORK ALTERING CASING OTHER: COMMENCE DEFILLING ONS. PLUG AND ABANDON CHANGE PLANS OTHER: OTHER: 12. Describe Proposed or Completed Operations (Clearly Issale all partitional details, and give pertiend date; including estimated date of istorting any proposed The Wilser Company of the State of S	DISTRICT I			WELL API NO.	
SAITA F.P., Now MEXICO 8/304-2083 5. Indicate Type of Lase STATE FEE 100 Not flows M. Asse, NM 87410 5. SUND R.M. NOTICES AND REPORTS ON WELLS SUND R.M. NOTICES AND REPORTS ON WELLS (DO NOT USE THIS PORTY OF PROCESSALS TO CRILL OR TO DEEPEN OF PUUG BACK TO A OFFICE OF WELL OTHER (DO NOT USE THIS PORTY OF PROCESSALS TO CRILL OR TO DEEPEN OF PUUG BACK TO A OFFICE OF WELL OTHER 1. Type of West OTHER The Wiser Oil Company Asset Operator The Wiser Oil Company S. Well No. 18 3. Address of Operator The Wiser Oil Company The Wiser Oil Company 10. Elevation (Show whether DF, RRS, RIC, R. etc.) 10. Elevation (Show whether DF, RRS, RIC, R. etc.) 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORABILY ABANDON CHANGE PLANS COMMENCE OF RILLING OPNS. PLUG AND ABANDONMENT TEMPORABILY ABANDON CHANGE PLANS COMMENCE OF RILLING OPNS. PLUG AND ABANDONMENT OTHER: OTHER: OTHER: OTHER: OTHER: OTHER: OTHER:	O. Box 1980, Hobbs, NM 88240 P.O. Box 2088		l l		
SUNDRY NOTICES AND REPORTS ON WELLS SUNDRY NOTICES AND REPORTS ON WELLS (CO NOT USE THIS FORM FOR PROPOSALS TO DRILL, OR TO DEEPEN OR PLUG BACK TO A IFFERENT RESPONSE TO THE COMMENT OF PROPOSALS TO DRILL, OR TO DEEPEN OR PLUG BACK TO A IFFERENT RESPONSE TO THE COMMENT OF PROPOSALS.) The Will Comment of Well Company 3. Address of Operator The Wilser Oil Company 3. Address of Operator The Wilser Oil Company 3. Address of Operator The Wilser Oil Company 3. Address of Operator Township 17. Raspe 332 NMPM Lea Comment NoTICE OF INTENTION TO: Socion 17. Township 18. Elevation (Show whether DP, RRB, RT, OR, etc.) 42081 To RRB, RT, OR, etc.) 42081 To RRB, RT, OR, etc.) 42081 To RRB, RT, OR, etc.) 18. Well No. 19. Pool same or Wildcat Mal jamar Grayburg San Andres 10. Elevation (Show whether DP, RRB, RT, OR, etc.) 42081 To RRB, RT, OR, etc.) 42081 To RRB, RT, OR, etc.) 19. Pool same or Wildcat Mal jamar Grayburg San Andres 10. Elevation (Show whether DP, RRB, RT, OR, etc.) 42081 To RRB, RT, OR, etc.) 42081 To RRB, RT, OR, etc.) 10. Elevation (Show whether DP, RRB, RT, OR, etc.) 42081 To RRB, RT, OR, etc.) 10. Elevation (Show whether DP, RRB, RT, OR, etc.) 42081 To RRB, RT, OR, etc.) 10. Elevation (Show whether DP, RRB, RT, OR, etc.) 11. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of storting any proposed 10. Elevation (Show whether DP, RRB, RT, OR, etc.) 11. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of storting any proposed 11. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of storting any proposed 11. Elevation (Show whether OP, RRB, RT, OR, etc.) 12. Describe Proposed or Completed Operations (Clearly state all pertinent dates), including estimated date of storting any proposed 12. Describe Proposed or Completed Operations (C	DISTRICT II Santa Fe, New Mexico 87504-2088 P.O. Drawer DD, Artesia, NM 88210		5. Indicate Type of Lease		
CONDINSE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DEFERENT RESERVOIR. US: *PAPILLATION FOR PERMITT (PORM C-101) FOR SUCH PROPOSALS.) 1. Type of Wal:	DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410			6. State Oil & Gas Lease No.	
CONDINSE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DEFERENT RESERVOIR. US: *PAPILLATION FOR PERMITT (PORM C-101) FOR SUCH PROPOSALS.) 1. Type of Wal:	SUNDRY NOTICES AND REPORTS ON WELLS				
2. Name of Operator 2. Name of Operator 3. Address of Operator 3. Address of Operator 4. Well Location 50 Box 1412, Artesia NM 88210-1412 4. Well Location 70 Box 1412, Artesia NM 88210-1412 4. Well Location 70 Box 1412, Artesia NM 88210-1412 4. Well Location 70 Box 1412, Artesia NM 88210-1412 4. Well Location 70 Box 1412, Artesia NM 88210-1412 71. Elevation (Show whether DF, RKB, RT, CR, etc.) 72. Range 33F NMPM Lea County 72.031 GR 72. GR. R. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data 72. NOTICE OF INTENTION TO: 72. SUBSEQUENT REPORT OF: 72. REMEDIAL WORK Appropriate Box to Indicate Nature of Notice, Report, or Other Data 72. NOTICE OF INTENTION TO: 72. REMEDIAL WORK ALTERING CASING 72. COMMENCE DRILLING OPNS. PLUG AND ABANDON FEMALY ABANDON CHANGE PLANS 72. COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT 72. Describe Proposed or Completed Operations (Clearly state all perinent details, and give perinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 72. SEE RULE 1103. 72. OTHER: 72. Describe Proposed or Completed Operations (Clearly state all perinent details, and give perinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 72. Commence Drilling of Section (Clearly state all perinent details, and give perinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 72. Commence Drilling of Section (Clearly state all perinent details, and give perinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 72. Commence Drilling of Section (Clearly state all perinent details, and give perinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 72. Commence Drilling of Section (Clearly state all perinent details, and give perinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 72. Commence Drilling of Section (Clearly state all perinent details, and give perinent dates, including estimated date of starting any propose	(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"			7. Lease Name or Unit Agreement Name	
The Wiser Oil Company 3. Address of Operator PO Box 1412, Artesia NM 88210-1412 4. Weil Leation Unit Letter Unit		OTHER		Western State	
3. Address of Operator PO Box 1412, Artesia NM 88210-1412 4. Well Location Unit Letter K : 1355 Feet From The South Line and 1351 Feet From The West Line Section 17 Township 17S Range 33E NMFM Lea County 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4208' GR 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT FEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT FEMPORARILY ABANDON OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent datasis, and give pertinent dates, including estimated date of starting any proposed worth) SEE RULE 1103. 07/12/5733 - Spud Well 07/12/5733 - Optid 12-1/4" hole to 1310'. Ran 29 jts.8-5/8" 24# J-55 casing & set @ 1310'. Cmt w/425 sx Halliburton Life & 250 sx Class "C" cmt. Circ 109 sx to pit. WOC 18 hrs. Test csg to 1000 psi for 30 min. No pressure loss. 08/105/93 - Orld 7-7/8" hole to 5500'. Ran 126 jts 5-1/2" J-55 csg & set @ 5500'. Cmt w/600 sx Halliburton Life & 750 sx Premium Plus cmt. Circ 125 sx to pit. WOC 18 hrs. Test csg to 1500 psi for 30 min. No pressure loss. 1 Intertry certly that the information appends the best or my knowledge and belief. 1 Perry Hughes, Agent TILLE 100. 1 TILLE 101. 1 Perry Hughes, Agent TILLE 102. 1 Perry Hughes, Agent TILLE 103. 1 Perry Hughes, Agent TILLE 104. 1 Perry Hughes, Agent TILLE 105. 1 Perry Hughes, Agent TILLE 106. 1 Perry Hughes, Agent TILLE 107. 1 Perry Hughes, Agent TILLE 108. 1 Perry Hughes, Agent TILLE 109. 1 Perry Hughes, Agent TILLE 109. 1 Perry Hughes, Agent TILLE 100. 1 Perry Hughes, Agent TILLE 100. 1 Perry Hughes, Agent TILLE 100. 100.	•	Oil Company			
Well Location West Line Section 17 Township 17S Range 33F NMPM Lea County 10. Elevation (Show whether PF, RKB, RT, GR, etc.) 4208 CR 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORABILLY ABANDON CHANGE PLANS CASING COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT TOWNSHIP THE COUNTY STATE AND CEMENT JOB OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent datalit, and give pertinent data, including estimated data of starring any proposed work) SER RULE 1103. OTHER:				9. Pool name or Wildcat	
Unit Letter K: 1355 Feet From The South Line and 1351 Feet From The West: Line Section 17 Township 175 Range 33E NMPM Lea Country 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4208¹ CgR	·				
Section 17 Township 17S Range 33E NMFM Lea County 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4208 1 GR 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT TOTHER: OTHER:	·				
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4208 ' GR 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: REMEDIAL WORK ALTERING CASING COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT TEMPORARILY ABANDON CHANGE PLANS CASING TEST AND CEMENT JOB OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 07/125/93 - Spud Well 07/127/93 - Drid 12-1/4" hole to 1310'. Ran 29 its 8-5/8" 24# J-55 casing & set @ 1310'. Cmt w/425 sx Halliburton Lite & 250 sx Class "C" cmt. Circ 109 sx to pit. WOC 18 hrs. Test csg to 1000 psi for 30 min. No pressure loss. 08/105/93 - Drid 7-7/8" hole to 5500'. Ran 126 its 5-1/2" J-55 csg & set @ 5500'. Cmt w/600 sx Halliburton Lite & 750 sx Premium Plus cmt. Circ 125 sx to pit. WOC 18 hrs. Test csg to 1500 psi for 30 min. No pressure loss. 1 hereby certify but psi information and only the market of my browledge and ballet. 1 hereby certify but psi information and only the market of my browledge and ballet. 1 hereby certify but psi information and only the market of my browledge and ballet. 1 hereby certify but psi information and only the my browledge and ballet. 1 hereby certify but psi information and only the my browledge and ballet. 1 hereby certify but psi information and only the my browledge and ballet. 1 hereby certify but psi information and only the my browledge and ballet. 1 hereby certify but psi information and only the my browledge and ballet. 1 hereby certify but psi information and only the my browledge and ballet. 1 hereby certify but psi information and only the my browledge and ballet. 1 hereby certify but psi information and only the my browledge and ballet. 1 hereby certify but psi information and only the my browledge and ballet. 1 hereby certify but psi information and only the my browledge and ballet. 1 hereby certify but psi information and	Unit Letter K : 13	55 Feet From The SOUTH	Line and1351	Feet From The West Line	
11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 13. O7/25/93 - Spud Well 14. O7/27/93 - Drid 12-1/4" hole to 1310'. Ran 29 jts 8-5/8" 24# J-55 casing & set @ 1310'. Cmt w/425 sx Halliburton Lite & 250 sx Class "C" cmt. Circ 109 sx to pit. WOC 18 hrs. Test csg to 1000 psi for 30 min. No pressure loss. 15. O8/05/93 - Drid 7-7/8" hole to 5500'. Ran 126 jts 5-1/2" J-55 csg & set @ 5500'. Cmt w/600 sx Halliburton Lite & 750 sx Premium Plus cmt. Circ 125 sx to pit. WOC 18 hrs. Test csg to 1500 psi for 30 min. No pressure loss. 1 hereby certify pur just information subspect for plue bate or my knowledge and bedief. 1 hereby certify pur just information subspect for plue bate or my knowledge and bedief. 1 hereby certify pur just information subspect for plue bate or my knowledge and bedief. 1 hereby certify pur just information subspect for plue bate or my knowledge and bedief. 1 hereby certify pur just information subspect for plue bate or my knowledge and bedief. 1 hereby certify pur just information subspect for plue bate or my knowledge and bedief. 1 hereby certify pur just information subspect for plue bate or my knowledge and bedief. 1 hereby certify pur just information subspect for plue bate or my knowledge and bedief. 1 hereby certify pur just information subspect for plue bate or my knowledge and bedief. 1 hereby certify pur just information subspect for plue bate or my knowledge and bedief. 1 hereby certify pur just information subspect for plue bate or my knowledge and bedief. 1 hereby certify pur just information subspect f	Section 17	Township 17S Ra	nge 33E	NMPM Lea County	
TIL. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT THER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 13. O7/25/93 - Spud Well 14. O7/27/93 - Drid 12-1/4" hole to 1310'. Ran 29 its 8-5/8" 24# J-55 casing & set @ 1310'. Cmt w/425 sx Halliburton Lite & 250 sx Class "C" cmt. Circ 109 sx to pit. WOC 18 hrs. Test csg to 1000 psi for 30 min. No pressure loss. 15. O8/05/93 - Drid 7-7/8" hole to 5500'. Ran 128 its 5-1/2" J-55 csg & set @ 5500'. Cmt w/600 sx Halliburton Lite & 750 sx Premium Plus cmt. Circ 125 sx to pit. WOC 18 hrs. Test csg to 1500 psi for 30 min. No pressure loss. 16. ORIGINAL SIGNED BY JERRY SEXTON ORIGINAL SIGNED BY JERRY SEXTON DISTRICT I SUPERVISOR			DF, RKB, RT, GR, etc.)	<i>\////////////////////////////////////</i>	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 14. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 15. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 16. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 18. Descri					
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING OTHER: OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 07/25/93 - Spud Well 07/27/93 - Ond 12-1/4" hole to 1310'. Ran 29 its 8-5/8" 24# J-55 casing & set @ 1310'. Cmt w/425 sx Halliburton Lite & 250 sx Class "C" cmt. Circ 109 sx to pit. WOC 18 hrs. Test csg to 1000 psi for 30 min. No pressure loss. 08/05/93 - Ond 7-7/8" hole to 5500'. Ran 126 its 5-1/2" J-55 csg & set @ 5500'. Cmt w/600 sx Halliburton Lite & 750 sx Premium Plus cmt. Circ 125 sx to pit. WOC 18 hrs. Test csg to 1500 psi for 30 min. No pressure loss. 1 hereby certify that the information showful true fool complete for the best of my knowledge and belief. Perry Hughes, Agent TITLE TYPE OR FRONT HAME TELEPHONE NO. SEP 2.9 1993					
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING CASING TEST AND CEMENT JOB OTHER: OTHER:	NOTICE OF IN	<u></u>			
CASING TEST AND CEMENT JOB OTHER: OT	PERFORM REMEDIAL WORK	[]			
OTHER: 12 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 07/25/93 - Spud Well 07/27/93 - Drid 12-1/4" hole to 1310'. Ran 29 jts 8-5/8" 24# J-55 casing & set @ 1310'. Cmt w/425 sx Halliburton Lite & 250 sx Class "C" cmt. Circ 109 sx to pit. WOC 18 hrs. Test csg to 1000 psi for 30 min. No pressure loss. 08/05/93 - Drid 7-7/8" hole to 5500'. Ran 126 jts 5-1/2" J-55 csg & set @ 5500'. Cmt w/600 sx Halliburton Lite & 750 sx Premium Plus cmt. Circ 125 sx to pit. WOC 18 hrs. Test csg to 1500 psi for 30 min. No pressure loss. I bereby certify that the information absorble true lead complete to the base or my knowledge and belief. SIGNATURE TITLE PETTY Hughes, Agent TITLE PETTY Hughes, Agent TITLE PETTY Hughes, Agent THE PETTY Hughes TELEPHONE NO.				r—	
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 07/25/93 - Spud Well 07/27/93 - Drid 12-1/4" hole to 1310'. Ran 29 jts 8-5/8" 24# J-55 casing & set @ 1310'. Cmt w/425 sx Halliburton Lite & 250 sx Class "C" cmt. Circ 109 sx to pit. WOC 18 hrs. Test csg to 1000 psi for 30 min. No pressure loss. 08/05/93 - Drid 7-7/8" hole to 5500'. Ran 126 jts 5-1/2" J-55 csg & set @ 5500'. Cmt w/600 sx Halliburton Lite & 750 sx Premium Plus cmt. Circ 125 sx to pit. WOC 18 hrs. Test csg to 1500 psi for 30 min. No pressure loss. 1 hereby certify that the information shows true food complete to the best or my knowledge and belief. SIGNATURE TITLE TYPE OR FRENT NAME Chair space for State Use) ORIGINAL SIGNED BY JERRY SEXTON DISTRICT I SUPERVISOR	PULL OR ALTER CASING CASING TEST AND C		EMENT JOB L		
O7/25/93 - Spud Well O7/27/93 - Drid 12-1/4" hole to 1310'. Ran 29 jts 8-5/8" 24# J-55 casing & set @ 1310'. Cmt w/425 sx Halliburton Lite & 250 sx Class "C" cmt. Circ 109 sx to pit. WOC 18 hrs. Test csg to 1000 psi for 30 min. No pressure loss. O8/05/93 - Drid 7-7/8" hole to 5500'. Ran 126 jts 5-1/2" J-55 csg & set @ 5500'. Cmt w/600 sx Halliburton Lite & 750 sx Premium Plus cmt. Circ 125 sx to pit. WOC 18 hrs. Test csg to 1500 psi for 30 min. No pressure loss. I hereby certify that use information absorbed to the best of my knowledge and belief. SIGNATURE TYPE OR PRINT HAMBE ORIGINAL SIGNED BY JERRY SEXTON DISTRICT I SUPERVISOR TITLE ORIGINAL SIGNED BY JERRY SEXTON DISTRICT I SUPERVISOR	OTHER:		OTHER:	L	
TYPE OR PRINT NAME ORIGINAL SIGNED BY JERRY SEXTON DISTRICT I SUPERVISOR THE Perry Hughes, Agent THE PERRY HUGHES, AG	work) SEE RULE 1103. 07/25/93 - Spud Well 07/27/93 - Drld 12-1/4" hole to 1310'. Ran 29 jts 8-5/8" 24# J-55 casing & set @ 1310'. Cmt w/425 sx Halliburton Lite & 250 sx Class "C" cmt. Circ 109 sx to pit. WOC 18 hrs. Test csg to 1000 psi for 30 min. No pressure loss. 08/05/93 - Drld 7-7/8" hole to 5500'. Ran 126 its 5-1/2" J-55 csg & set @ 5500'. Cmt w/600 sx Halliburton Lite & 750 sx				
DISTRICT I SUPERVISOR	SIGNATURE . TYPE OR PRINT NAME	Jughes "	Delet. Perry Hughes	DATE	
	(This space for State Use) ORIGINAL SI APPROVED BY DISTS	GNED BY JERRY SEXTON RICT I SUPERVISOR	n.e	SEP 2 9 1993	

mer was now that I shall be

SEP 2 8 1993

ی OFFICE