

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brison Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-32164
5. Indicate Type of Lease STATE ☒ FEE ☐
6. State Oil & Gas Lease No. B 3510
7. Lease Name or Unit Agreement Name ANDERSON RANCH UNIT
8. Well No. 21
9. Pool name or Wildcat WILDCAT ELLENBURGER

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well ☐ GAS WELL ☐ OTHER DRY HOLE	
2. Name of Operator CONOCO INC. <005073>	
3. Address of Operator 10 Desta Drive Ste 100 W. Midland, TX 79705	
4. Well Location SH Unit Letter T : 1700 / 1691 SOUTH 850 / 715 WEST Section 1 Township 16 S Range 32 E NMPM LEA County	
10. Elevation (Show whether DF, RCB, RT, GR, etc.) GL 4295: KB 4322	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐	ALTERING CASING ☐
PULL OR ALTER CASING ☐	COMMENCE DRILLING OPNS. ☐
OTHER ☐	PLUG AND ABANDONMENT ☒
	CASING TEST AND CEMENT JOB ☐
	OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

7-8-94 MIRU DA&S OIL WELL SERVICING INC. BLEED WELL TO TEST TANK. KILL WELL. UNSEAT PACKER. POOH. RIH W/ CEMENT RETAINER SET @ 12,085'. STING INTO RETAINER PUMP 25 SX CLASS 'H' CMT UNDER RETAINER @ 1000#. STING OUT AND SPOT 15 SX CLASS 'H' ON TOP OF RETAINER FROM 12,085' - 11,995'. PUH TO 8950' AND SPOT 25 SX CLASS 'C' CMT FROM 8950' TO 8000'. POOH. CUT 7" CSG @ 5700'. TRY TO WORK FREE. COULD NOT PULL. GIH W/ TBG TO 5750'. SPOT 35 SX CLASS 'C' CMT FROM 5750' TO 5540'. PUH TO 4260'. SPOT 35 SX CLASS 'C' CMT. POOH. GIH TAG CMT @ 4020'. POOH. GIH CUT 7" CSG # 3700'. PULL CSG OUT OF HOLE & LAY DOWN. GIH W/ TBG TO 3750'. SPOT 40 SX CLASS 'C' CMT. TAG CMT @ 3619'. PUH TO 1450' AND SPOT 45 SX CLASS 'C' CMT FROM 1450' TO 1315'. PULL TBG TO 600'. CIRCULATE 200 SX CLASS 'C' CMT FROM 600' TO SURFACE. CUT OFF WELLHEAD AND INSTALL P&A MARKER.
7-18-94 RDMO.

BUDDY HILL W/ NMOC D WITNESSED THE PROCEDUER AND INDICATED THAT IT WAS OK.
THE WELL BORE WAS FILLED W/ 25# SALT GEL MUD.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Bill R. Keathly TITLE SR. REGULATORY SPEC. DATE 8-9-94
TYPE OR PRINT NAME BILL R. KEATHLY TELEPHONE NO. 915-686-5424

(This space is for State Use)

APPROVE BY [Signature] TITLE OIL & GAS INSPECTOR DATE 8-9-94
CONDITIONS OF APPROVAL, IF ANY: