

**DISTRICT I**

P. O. Box 1980, Hobbs, NM 88240

**DISTRICT II**

P. O. Drawer DD, Artesia, NM 88210

**DISTRICT III**

1000 Rio Brazos Rd., Aztec, NM 87410

**OIL CONSERVATION DIVISION**

P. O. Box 2088  
Santa Fe, NM 87504-2088

WELL API NO.

30-025-32422

5. Indicate Type of Lease

STATE ☒

FEE ☐

6. State Oil & Gas Lease No.

B-2148

7. Lease Name or Unit Agreement Name  
Caprock Maljamar Unit

**SUNDRY NOTICES AND REPORTS ON WELLS**

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR, USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1 Type of Well:

OIL ☐

GAS ☐

WELL ☐

WELL ☐

OTHER TA

2. Name of Operator

The Wiser Oil Company

8. Well No.

153

3. Address of Operator

P.O. Box 2568 Hobbs, New Mexico 88241 (505) 392-9797

9. Pool name or Wildcat

Maljamar Grayburg San Andres

4. Well Location

Unit Letter N : 1299 Feet From The South Line and 2597 Feet From The West ine

Section 17 Township 17S Range 33E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

4200'

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

**NOTICE OF INTENTION TO**

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

**SUBSEQUENT REPORT OF:**

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: TA ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

02/26/01 MIRU Key Well Service # 438. Could not pull rods & pump. LD PR & PRL. ND WH. RU BOP. Turned tbq. to release TAC & tbq. parted. RIH w/7/8" x 1" rod coupling on 1". Tagged & screwed onto rods. POH. LD rods & pump w/no lift sub & 1-1/4" x 6' GA.

02/27/01 POH & LD 100 jts. 2-7/8" tbq. RD BOP. NU WH. RDMO. Waiting on engineering.

03/22/01 MIRU Key Well Service. ND WH. RU BOP. RIH w/4-3/4" bit & sub. Picked up 138 jts. 2-7/8" tbq. Tagged fish @ 4480'. Pushed down to 4500'. POH w/tbg. LD tools. RIH w/5-1/2" CIBP on 2-7/8" tbq. to 4088' & set CIBP. Circulated 90 bbls. pkr. fluid. Tested to 500# for 30 min. POH. LD 2-7/8" tbq. RD BOP. NU WH. RDMO. Well is TA'D.

This Approval of Temporary  
Abandonment Expires

10/16/06

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Mary Jo Turner  
TYPE OR PRINT NAME Mary Jo Turner

TITLE Production Tech II DATE September 14, 1999  
TELEPHONE NO. 392-9797

(This space for State Use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE OCT 12 2001

