

DISTRICT I
1625 French Drive Hobbs, NM 88240

DISTRICT II
P. O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P. O. Box 2088
Santa Fe, NM 7504-2088

WELL API NO.

30-025-32423

5. Indicate Type of Lease

STATE ☒

FEE ☐

6. State Oil & Gas Lease No.

B-2148

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR, USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL

WELL ☒

GAS

WELL ☐

OTHER

2. Name of Operator

The Wiser Oil Company

3. Address of Operator

P.O. Box 2568 Hobbs, New Mexico (505) 392-9797

8. Well No.

180

9. Pool name or Wildcat

Maljamar Grayburg San Andres

4. Well Location

Unit Letter C : 1287 Feet From The North Line and 2609 Feet From The West Line

Section 20 Township 17S Range 33E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

4184' GR

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: Pin Break ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

6/06/02 MIRU Key Well Service. POH w/rods. Pin break 3/4" on 89th rod. Fish rods & pump. ND WH. RU BOP. POH w/2-7/8" tbg., TAC & BHA.

6/07/02 RIH w/cutrite shoe, wash pipe, DC's & jars on 2-7/8" tbg.. Tag @ 4212'. Cut over junk 4212'. Circulate hole clean. POH above the perf.

6/10/02 RIH w/cutrite shoe, wash pipe, DC's & jars on 2-7/8" tbg. to 4237'. Wash over to 4244'. POH w/tbg. & tools. LD shoe.

6/11/02 RIH w/cutrite shoe, wash pipe, DC's & jars on 2-7/8" tbg. to 4244'. Wash over to 4245'. Lost torque. POH w/tbg. & tools. Bottom jt. wash pipe broken off at bottom pin. Shoe in hole. RIH w/2-7/8" overshot, & DC's on 2-7/8" tbg. Caught fish @ 4210'. POH w/tbg. & tools. Fish was 26' 2-7/8" tbg. Left in hole 1 1/2 jts. 2-7/8" tbg., SN, MSMA & 20' pump.

6/12/02 RIH w/2-7/8" overshot, jars & DC's on 2-7/8" tbg. Caught fish @ 4236'. Jar loose. POH w/tbg. & tools. Fish was 3' of 2-7/8" tbg. RIH w/tools & tbg. to 4239'. Caught fish but could not stay on. POH w/tbg. & tools. Had 16' of pump barrel caught in overshot.

6/13/02 RIH w/2-7/8" tbg. Tbg. @ 4200'. SN @ 4170'. RD BOP. NU WH. RIH w/rods & 1-1/2" x 20' pump. Left well pumping to CMU Battery "A". RDMO.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Mary Jo Turner
TYPE OR PRINT NAME Mary Jo Turner

TITLE Production Tech II

DATE July 25, 2002

TELEPHONE NO. (505) 392-9797

(This space for State Use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

DATE

AUG 07 2002

ORIGINAL SIGNED BY

GARY W. WINK

OC FIELD REPRESENTATIVE II/STAFF MANAGER