

DISTRICT I
P. O. Box 1980, Hobbs, NM 88240

DISTRICT II
P. O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P. O. Box 2088
Santa Fe, NM 87504-2088

WELL API NO. 30-025-32426
5. Indicate Type of Lease STATE ☒ FEE ☐
6. State Oil & Gas Lease No. B-2149

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. Lease Name or Unit Agreement Name Caprock Maljamar Unit
2. Name of Operator The Wiser Oil Company	8. Well No. 176
3. Address of Operator P.O. Box 2568 Hobbs, New Mexico 88241 (505) 392-9797	9. Pool name or Wildcat Maljamar Grayburg San Andres
4. Well Location Unit Letter <u>B</u> : <u>1305</u> Feet From The <u>North</u> Line and <u>2625</u> Feet From The <u>East</u> Line Section <u>19</u> Township <u>17S</u> Range <u>33E</u> NMPM <u>Lea</u> County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4119' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐	ALTERING CASING ☐
PULL OR ALTER CASING ☐	COMMENCE DRILLING OPNS. ☐
OTHER: ☐	PLUG AND ABANDONMENT ☐
	CASING TEST AND CEMENT JOB ☐
	OTHER: <u>Re-perf. & acidize</u> ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

8/26/00 RIH w/tools & tbg. Set RBP @ 4332'. Set pkr. @ 4248'. Test tbg. to 4000#. Held. RU Petroplex Well Service. Acidized Vac. f/4303'-4310' w/1000 gals. 15% HCL NE-FE acid w/25 ball sealers. Balled out. ATP 2500# @ 1.7 bpm. MTP 3025# @ 2.1 bpm. ISIP 2500#. 5 min. 1934#. 10 min. 1693#. 15 min. 1566#. Flush w/25 bbls. water. 1 hr. SI 1209#. Moved RBP to 4248'. Pkr. @ 3945'. Test csg. to 500#. Acidized Grayburg f/4001'-4208' w/3000 gals. 15% HCL NE-FE acid w/2750# rock salt. Best block 500#. Best break 500#. ATP 3200# @ 4.0 bpm. MTP 4026# @ 4.2 bpm. ISIP 2523#. 5 min. 2325#. 10 min. 2176#. 15 min. 2056#. Flush w/29 bbls. RD Petroplex. 1 hr. SI 1813#. POH w/2-7/8" tbg. LD RBP & pkr. RIH w/2-7/8" tbg. Tbg. @ 4000'. SN @ 3970'. TAC @ 3680'.

8/29/00 RD BOP. NU WH. RIH w/rods & 2-1/2" x 1-1/2" x 20' RHBC pump. Left well pumping to CMU Battery "B".

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Mary Jo Turner TITLE Production Tech II DATE October 18, 2001

TYPE OR PRINT NAME Mary Jo Turner

(This space for State Use)

APPROVED BY

TITLE PAULETTE DATE 10/18/01

ORIGINAL SIGNED BY
PAULETTE
PETROLEUM