

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
310 Old Santa Fe Trail, Room 206
Santa Fe, New Mexico 87503

WELL API NO. 30-025-32573
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Anderson 33
8. Well No. 1
9. Pool name or Wildcat West Knowles - Strawn
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 1723.5' DF; 3707' GR

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	
2. Name of Operator Anson Gas Corporation	
3. Address of Operator P. O. Box 24060 - Oklahoma City, OK 73124	
4. Well Location Unit Letter <u>J</u> ; <u>2520'</u> Feet From The <u>South</u> Line and <u>2310'</u> Feet From The <u>East</u> Line Section <u>33</u> Township <u>16S</u> Range <u>38E</u> NMPM <u>Lea</u> County <u></u>	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 1723.5' DF; 3707' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Strawn formation depleted @ 11321-26' 11330-43'. Pulled rods, tubing and packer. Set CIBP @ 11,000' w/35' cement on top. Attempted to complete in Abo 9104-12 & 9118-26' without success. Well Temp. abandoned until offset drilling results are evaluated from our Mary 33-1. If the Mary 33-1 is productive, an evaluation will be made on re-entry of this well or P&A.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Jerry Northcutt TITLE V.P. - Expl & Prod. DATE 5-4-95
TYPE OR PRINT NAME Jerry Northcutt TELEPHONE NO. (405) 528-0525

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

MAY 12 1995