

**DISTRICT I**

P. O. Box 1980, Hobbs, NM 88240

**DISTRICT II**

P. O. Drawer DD, Artesia, NM 88210

**DISTRICT III**

1000 Rio Brazos Rd., Aztec, NM 87410

**OIL CONSERVATION DIVISION**

2040 South Pacheco  
Santa Fe, New Mexico 86595

WELL API NO.  
30-025-32580

5. Indicate Type of Lease  
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.  
VA-903

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT  
(FORM C-101) FOR SUCH PROPOSALS)

1. Type of Well:

Oil Well ☒ Gas Well ☐ OTHER

2. Name of Operator

TMBR/Sharp Drilling, Inc.

3. Address of Operator

P. O. Drawer 10970, Midland, TX 79702

4. Well Location

Unit Letter E : 2414 Feet From The North Line and 1109 Feet From The West

Section 36 Township 16S Range 37E NMPM County Lea

10. Elevation (Show whether DF, RKB, RT, GR, etc.)  
3753' GR

7. Lease Name or Unit Agreement Name

Gecko State "36"

8. Well No.

1

9. Pool name or Wildcat

Shipp (Strawn)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

**NOTICE OF INTENTION TO:**

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

**SUBSEQUENT REPORT OF:**

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDON ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

See attachments.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

*Jeffrey D. Phillips*  
Jeffrey D. Phillips

TITLE

Vice President

DATE

05/10/99

TYPE OR PRINT NAME

TELEPHONE NO.

(915) 699-5050

(This space for State Use)

ORIGINAL SIGNED BY  
GARY L. [unclear]  
[unclear]

APPROVED BY

TITLE

DATE

NOV 22 1999

CONDITIONS OF APPROVAL, IF ANY:

✓  
ds

TMBR/Sharp Drilling, Inc.  
Gecko State 36 #1  
Sec. 36, T16S, R-37E  
Lea County, New Mexico

12. Describe Proposed or Completed Operations.

Plugging Instructions Per Verbal Approval from Gary Wink NMOCD Hobbs  
verbal approval received 5/6/99 by Jeff Phillips, TMBR/Sharp Drilling.

1. TIH w/ 5 1/2" 17# Cement retainer on 2 7/8" AOH Drill pipe. Set CRT at  $\pm 6,400'$  and pump the cement volume of the 5 1/2" casing (550sx) from 6,400' to 11,684' below the CRT.
2. Sting out and dump  $\pm 5$  sx of cement on top of retainer.
3. POOH to  $\pm 4,530'$  and spot 100' (25 sx) plug in 5 1/2" casing from 4,530' to 4,430'.
4. TOH and stand back  $\pm 3,000'$  of 2 3/8" tubing.
5. GIH and freepoint and jet cut casing at  $\pm 2,950'$ . Pull and LD 5 1/2" casing.
6. TIH with 2 3/8" tubing to 50' inside of 5 1/2" stubb, wherever that is, and spot 100' plug in/out. (Alternate Plug: Perf and squeeze at  $\pm 2,950'$ , a 50' plug in/out) **NOTE: 9 5/8" casing set to 4470' with cement circulated to surface.** (35sx)
7. TOH 10 stands and WOC 4 hrs. TIH and **TAG plug at  $\pm 2,900'$ .**
8. TOH to 500' and spot 100' plug (35 sx) in 9 5/8" casing from 500' to 400'. **NOTE: 13 3/8" casing set to 452' with cement circulated to surface.**
9. TOH and spot 10 sx surface plug from 30' to surface.
10. Install monument with operator data welded on as per NMOCD Rules.

TMBR Sharp Drilling, Inc  
Gecko State 36-  
Sec 36, T16S, R37E  
Lea County, NM

