

DISTRICT I
1625 French Drive Hobbs, NM 88240

DISTRICT II
P. O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P. O. Box 2088
Santa Fe, NM 7504-2088

WELL API NO.

30-025-32839

5. Indicate Type of Lease

STATE ☒

FEE ☐

6. State Oil & Gas Lease No.

B-2148

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR, USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

7. Lease Name or Unit Agreement Name

Caprock Maljamar Unit

1 Type of Well:

OIL
WELL ☒

GAS
WELL ☐

OTHER

2. Name of Operator

The Wiser Oil Company

8. Well No.

142

3. Address of Operator

P.O. Box 2568 Hobbs, New Mexico (505) 392-9797

9. Pool name or Wildcat

Maljamar Grayburg San Andres

4. Well Location

Unit Letter J : 2544 Feet From The South Line and 2546 Feet From The East Line

Section 17 Township 17S Range 33E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

4206' GR

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: Collapsed casing ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

4/18/02 MIRU Eunice Well Service. POH w/rods to 4515'. Back off rods. POH w/rods, pumps top mandrel traveling valve & plunger. Barrel & standing valve left in hole. TAC would not unset. Tbg. stuck. RU Computalog WL & ran freepoint. Stuck @ 4072'. Tag collapsed tbg. T 4510'. Chemical cut tbg. @ 4453'. Blast TAC @ 4072'. Chemical cut tbg. @ 4057'. RD WL. POH w/2-7/8" tbg. RIH w/overshot, bumper sub, Johnson jars & DC's on 2-7/8" tbg.

4/19/02 Caught fish @ 4055'. POH w/1/2 jt. 2-7/8" tbg., TAC & 12-1/2 jts. 2-7/8" tbg. Chemical cut @ 4453' end of fish. LD fish. RIH w/overshot, bumper sub, Johnson jars & DC's on 2-7/8" tbg. Caught fish @ 4453'. Jar fish to 4450'. Release fish. POH w/tbg. & DC's. LD tools.

4/22/02 RIH w/cutrite shoe, wash pipe & DC's on 2-7/8" tbg. Tag @ 4515'. Wash over to 4525'. Circulate hole clean. Pull to 4000'.

4/23/02 TIH @ 4495'. Wash over fish @ 4500'. RIH w/2-7/8" tbg., wash pipe & shoe. Milled over fish to 4505'. POH w/tbg. to 4000'.

4/24/02 RIH and tag fish. Mill to 4510'. Circulate hole clean. Losing 30 bbls. water per hr.

4/26/02 RIH w/overshot & bumper sub on 2-7/8" tbg. to 4534'. RU Rotary WL. RIH w/freepoint & collar locator. No fish @ 4534'. POH w/2-7/8" tbg. LD all DC's & tools. Release WL. RIH w/2-7/8" tbg. Tbg. @ 4226'. SN @ 4192'. RD BOP. NU WH. RIH w/rods & 1-1/2" x 20' pump. Left well pumping to CMU Battery "A". RDMO.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Mary Jo Turner
TYPE OR PRINT NAME Mary Jo Turner

TITLE Production Tech II

DATE June 25, 2002

TELEPHONE NO. (505) 392-9797

(This space for State Use)

APPROVED BY

ORIGINAL SIGNED BY
GARY W. WINK
TITLE
OC FIELD REPRESENTATIVE II/STAFF MANAGER

DATE JUL 2 2002

CONDITIONS OF APPROVAL, IF ANY: