

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-32861
5. Indicate Type of Lease	STATE ☒ FEE ☐
6. State Oil & Gas Lease No.	VA4119
7. Lease Name or Unit Agreement Name	Gecko State "35"
8. Well No.	2
9. Pool name or Wildcat	Casey (Strawn)

1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER ☐	2. Name of Operator TMBR/Sharp Drilling, Inc.
3. Address of Operator P.O. Drawer 10970, Midland, Texas 79702	4. Well Location Unit Letter <u>G</u> : <u>1874</u> Feet From The <u>North</u> Line and <u>1874</u> Feet From The <u>East</u> Line Section <u>35</u> Township <u>16S</u> Range <u>37E</u> NMPM Lea County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3773 KB	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL WELL ☒

GAS WELL ☐

OTHER ☐

2. Name of Operator

TMBR/Sharp Drilling, Inc.

3. Address of Operator

P.O. Drawer 10970, Midland, Texas 79702

4. Well Location

Unit Letter G : 1874 Feet From The North Line and 1874 Feet From The East Line

Section

35

Township

16S

Range

37E

NMPM

Lea

County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

3773 KB

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

2/9/00 Wireline set 5-1/2" CIBP @ 11450. Circulate hole w/10# gel.

2/10/00 Spot 25 sx cmt from 11450 to 11225.

2/10/00 Spot 25 sx cmt from 8925 to 8700.

2/10/00 Spot 25 sx cmt from 6530 to 6280.

2/11/00 Cut and Pull 5-1/2" csg. from 5300.

2/11/00 Spot 45 sx cmt from 5350 to 5725. WOC Tag TOC @ 5107.

2/14/00 Spot 60 sx cmt from 4600 to 4385. WOC Tag TOC @ 4380.

2/14/00 Spot 50 sx cmt from 2140 to 1960.

2/14/00 Spot 50 sx cmt from 500 to 300. WOC Tag TOC @ 360.

2/15/00 Spot 10 sx cmt from 30' to Surface.

2/16/00 Cut off wellhead 4' below Surface. Install dry hole marker.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Roger Massey

TITLE

Area Manager

DATE

2-25-00

TYPE OR PRINT NAME

Roger Massey

TELEPHONE NO. 915-699-50

(This space for State Use)

APPROVED BY

Johnny Robinson
GWW

TITLE

COMPLIANCE OFFICER

DATE

JAN 22 2003

