

DISTRICT I  
P. O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P. O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

**OIL CONSERVATION DIVISION**  
P. O. Box 2088  
Santa Fe, NM 7504-2088

WELL API NO. 30-025-32924
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. B-2148
7. Lease Name or Unit Agreement Name Caprock Maljamar Unit
8. Well No. 143
9. Pool name or Wildcat Maljamar Grayburg San Andres
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4205' GR

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR, USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL <input type="checkbox"/> GAS <input type="checkbox"/> WELL <input type="checkbox"/> WELL <input type="checkbox"/> OTHER TA	
2. Name of Operator The Wiser Oil Company	
3. Address of Operator P.O. Box 2568 Hobbs, New Mexico (505) 392-9797	
4. Well Location Unit Letter J : 2560 Feet From The South Line and 1409 Feet From The East Line Section 17 Township 17S Range 33E NMPM Lea County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4205' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
<b>NOTICE OF INTENTION TO</b>	<b>SUBSEQUENT REPORT OF:</b>
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
OTHER: <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
	COMMENCE DRILLING OPNS. <input type="checkbox"/>
	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input checked="" type="checkbox"/> Temporarily Abandon

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

07/31/00 MIRU Key Well Service. ND WH. RU BOP. POH w/2-7/8" tbg. LD Reda ESP w/Cavins desander. Spooled cable. RIH w/5-1/2" CIBP on 2-7/8" tbg. Set plug @ 4189'. Pulled up and circulated 90 bbls. pkr. fluid. Tested plug to 500# for 15 minutes. Held ok. POH w/2-7/8" tbg. LD 134 jts. LD CIBP and setting tool. RD BOP. NU WH w/2-7/8" x 4' sub and valve on top. RDMO. Well is TA'D.

This Approval of Temporary  
Abandonment Expires 1/12/2006

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Mary Jo Turner TITLE Production Tech II DATE December 19, 2000  
TYPE OR PRINT NAME Mary Jo Turner TELEPHONE NO. (505) 392-9797

(This space for State Use)

APPROVED BY \_\_\_\_\_ TITLE DISTRICT I SUPERVISOR DATE \_\_\_\_\_

