Submit 3 Copies to Appropriate

## State of New Mexico Energy, Minerals & Natural Resources Department

Form C-103 Revised 1-1-89

District Office	2110181, 1121101111111111111111111111111111111		
DISTRICT I	OIL CONSERVATION DIVISION P. O. Box 2088 Santa Fe, NM 87504-2088		WELL API NO.
P. O. Box 1980, Hobbs, NM 88240			30-025-33005
			5. Indicate Type of Lease
DISTRICT II  P. O. Drawer DD, Artesia, NM 88210  Santa Fe, NM 87504-2088		STATE FEE	
1. 0. 2			6. State Oil & Gas Lease No.
DISTRICT III			B-2148
1000 Rio Brazos Rd., Aztec. NM 87410 SUNDRY NOTICES AND REPORTS ON WELLS			
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A		7. Lease Name or Unit Agreement Name	
DIFFERENT RESERVOIR, USE "APPLICATION FOR PERMIT"		Caprock Maljamar Unit	
	101) FOR SUCH PROPOSALS.)		
1 Type of Well: OIL GAS			
WELL WELL	OTHER		
2. Name of Operator			8. Well No.
The Wiser Oil Company			159
3. Address of Operator		9. Pool name or Wildcat	
P.O. Box 2568 Hobbs, New	w Mexico 88241 (505) 392-	9797	Maljamar Grayburg San Andres
4. Well Location			
0 475	Cth	. 1250	Feet From The East ine
Unit Letter <u> </u>	Feet From The South	Line and 1336	Feet From The <u>East</u> ine
n .: 12	nship 17S Range	<del></del>	NMPM Lea County
Section 13 Tow			WINI M Bod County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4097' GR			
Charles American Dougle Indicate Nature of Notice Report or Other Data			
NOTICE OF INTENTION TO SUBSEQUENT REPORT OF:			
NOTICE OF INT	ENTION TO	3000	
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
			DIVID AND ADAMSON THE
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING	OPNS. PLUG AND ABANDONMENT
CALCING TEST AND SEME			15.17 LOD
PULL OR ALTER CASING		CASING TEST AND CEN	MENT JOB L
OTHER:		OTHER: Re-perf. & a	acidize
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed			
work) SEE RULE 1103.			
NO. 1 O NO. 1			
7/11/00 MIRU Tyler Well Service. POH w/rods & pump. ND WH. RU BOP. POH w/tbg. RIH w/4-3/4" bit & scraper on 2-7/8"			
tbg. Tag @ 4250'. POH w/2-7/8" tbg. LD bit & scraper.			
Company of the Compan			
7/12/00 RU Computalog WL. RIH w/CIBP. Tag @ 4250'. Set CIBP top of plug @ 4245'. Perforate San Andres Grayburg f/3960',			
68',69',4007',08',09',35',66',67',97',4108',09',13',14',26',27',44'',45',53',60',63',67',73',76',80', & 85' w/4 SPF. RD WL.			
RIH w/5-1/2" AD-1 pkr. on 2-7/8" tbg. to 3907'. Set pkr. RU Hughes Well Service. Drop standing valve. Test tbg. to			
4000#. Csg. to 500#. Acidized San Andres Grayburg 3960'-4185' w/3000 gals. 15% HCL NE-FE acid in 6 stages w/2750#			
rock salt in 5 stages. Max. block to 4000#. Best break 3450#. ATP 3750# @ 4.0 bpm. MTP 4000# @ 4.5 bpm. Flushed			
w/29 bbls. water. ISIP 2920#. 5 min. 2600#. 10 min. 2550#. 15 min. 2500#. RD Hughes. SI 1 hr. 2200#.			
The location of the state of th			
7/13/00 POH w/2-7/8" tbg. LD AD-1 pkr. RIH w/rods & 2-1/2" x 1-1/2" x 20' RHBC pump. Left well pumping to CMU Battery "B".			
RDMO.			
I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
SIGNATURE Many Oo Turner TYPE OR PRINT NAME Mary Jo Turner		TITLE Producti	on Tech II DATE June 14, 2001 TELEPHONE NO. 392-9797
			I BERTIONE NO. 372-7171
(This space for State Use)		······································	
		TITLE	DATE
APPROVED BY		11 LE	
			1