

Denton North Wolfcamp Unit Well No. 633
API No. 30-025-33090
1458 FNL & 1347 FEL, Unit 'G', Section 35
Township 14 South, Range 37 East, NMPM
Injection Interval: 9,170 feet to 9,300 feet
Maximum Injection Pressure: (.2 psi/ft) 1834

Lea County, New Mexico.

IT IS FURTHER ORDERED THAT:

The operator shall take all steps necessary to ensure that the injected water enters only the proposed injection interval and is not permitted to escape to other formations or onto the surface.

Prior to commencing injection operations into the well(s), the casing shall be pressure tested from the surface to the packer setting depth to assure the integrity of said casing.

The casing-tubing annulus shall be loaded with an inert fluid and equipped with a pressure gauge at the surface or left open to the atmosphere to facilitate detection of leakage in the casing, tubing or packer.

The injection well(s) or system shall be equipped with a pressure limiting device which will limit the wellhead pressure on the injection well(s) to no greater than .2 psi per foot of depth to the uppermost injection perforations.

The Director of the Division may authorize an increase in injection pressure upon a proper showing by the operator of said well(s) that such higher pressure will not result in migration of the injected fluid from the Wolfcamp formation. Such proper showing shall consist of a valid step-rate test run in accordance with and acceptable to this office.

The operator shall notify the supervisor of the Hobbs district office of the Division of the date and time of the installation of injection equipment and of the mechanical integrity tests so that the same may be inspected and witnessed.

The operator shall immediately notify the supervisor of the Hobbs district office of the Division of the failure of the tubing, casing or packer in said well(s) and shall take such steps as may be timely and necessary to correct such failure or leakage.

The subject well(s) shall be governed by all provisions of Division Order No. R-3001, as amended and Rules 702-706 of the Division Rules and Regulations not inconsistent herewith.