

DISTRICT I
P. O. Box 1980, Hobbs, NM 88240

DISTRICT II
P. O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P. O. Box 2088
Santa Fe, NM 7504-2088

WELL API NO. 30-025-33270
5. Indicate Type of Lease STATE ☒ FEE ☐
6. State Oil & Gas Lease No. B-2148

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR, USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. Lease Name or Unit Agreement Name Caprock Maljamar Unit
2. Name of Operator The Wiser Oil Company	8. Well No. 207
3. Address of Operator P.O. Box 2568 Hobbs, New Mexico	9. Pool name or Wildcat Maljamar Grayburg San Andres
4. Well Location Unit Letter O : 1234 Feet From The South Line and 1404 Feet From The East Line Section 19 Township 17S Range 33E NMPM Lea County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4087' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐	ALTERING CASING ☐
PULL OR ALTER CASING ☐	COMMENCE DRILLING OPNS. ☐
OTHER: ☐	PLUG AND ABANDONMENT ☐
	CASING TEST AND CEMENT JOB ☐
	OTHER: Perf. & acidize ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

9/04/01 MIRU Tyler Well Service. POH w/rods & pump. Pump barrel broken. NU BOP. POH w/2-7/8" tbg. Found hole in blast jt. RIH w/4-3/4" bit & scraper on 2-7/8" tbg. to 4454'. POH w/bit, scraper & 2-7/8" tbg.

9/05/01 RU Computalog WL & perforate Grayburg f/ 4058'-59',60',88'-92',96',4125'-28',76',81',82',4198'-4201',16'-21',34'-40',44'-52',58',59',63'-66',75', & 83' & Vacuum f/4334'-40' w/4 SPF. RD WL. RU Hydrostatic testers & test tbg. RIH w/RBP, pkr. & 2-7/8" tbg. Set RBP @ 4358'. POH. Set pkr. @ 4000'. Spot 400 gals. toluene across perms. Drop standing valve.

9/06/01 Fish standing valve & swab back toluene. RIH w/pkr. Set @ 4305'. Acidize Vacuum perms. 4334'-4353' w/700 gals. 15% NE-FE acid 3 bpm @ 3800#. ISIP 2500#. 5 min. 2430#. 10 min. 2410#. 15 min. 2400#. SI 1 hr. POH w/RBP & set @ 4305'. Set pkr. @ 3996'. Acidize Grayburg perms. 4058'-4288' w/2300 gals. 15% NE-FE acid w/3500# rock salt. Flush w/35 bbls. fresh water. ISDP 1700#. 5 min. 1300#. 10 min. 1050#. 15 min. 950#. SI 1 hr. Circulate w/30 bbls. fresh water. RD Hughes. POH w/RBP, pkr. & 2-7/8" tbg.

9/07/01 RIH w/2-3/8" tbg. 1bgt. @ 4439'. SN @ 4408'. RIH w/2" x 1-1/2" x 20' pump. Left well pumping to Battery.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Mary Jo Turner TITLE Production Tech II DATE January 14, 2002
TYPE OR PRINT NAME Mary Jo Turner TELEPHONE NO. (505) 392-9797

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE _____

ORIGINAL FILED BY
TITLE FILED
PETROLEUM ENGINEER
JAN 28 2002
DATE