

DISTRICT I
P. O. Box 1980, Hobbs, NM 88240

DISTRICT II
P. O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P. O. Box 2088
Santa Fe, NM 7504-2088

WELL API NO.	30-025-33270
5. Indicate Type of Lease	STATE ☒ FEE ☐
6. State Oil & Gas Lease No.	B-2148

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR, USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

7. Lease Name or Unit Agreement Name
Caprock Maljamar Unit

1. Type of Well:
OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. Name of Operator
The Wiser Oil Company

8. Well No.
207

3. Address of Operator
P.O. Box 2568 Hobbs, New Mexico

9. Pool name or Wildcat
Maljamar Grayburg San Andres

4. Well Location
Unit Letter O : 1234 Feet From The South Line and 1404 Feet From The East Line
Section 19 Township 17S Range 33E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
4087' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data			
NOTICE OF INTENTION TO		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☒	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐		CASING TEST AND CEMENT JOB ☐	
OTHER: ☐		OTHER: ☐	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

9/03/97 MIRU Ram Well Service. POH w/rods & pump. ND WH. NU BOP. Release TAC. POH w/2-7/8" tbg. Tag @ 4463'. RIH w/perf clean assembly, 10 jts. 2-7/8" tbg., AD-1 pkr. & 100 jts. 2-7/8" tbg. to 3500'.

9/04/97 RU HES & pump fresh water on perf clean f/4050'-4110'. POH & LD pkr. RIH w/perf. clean tool & 2-7/8" tbg. Perf clean f/4050'-4360'. Wash w/1000 gals. 15% NE-FE acid f/4360'-4050'. RIH to 4470' & circulate well. Pull to 1600'.

9/05/97 POH & LD tools. RIH w/AD-1 pkr. & 2-7/8" tbg. Set pkr. @ 3950'. HES pump 3000 gals. 15% NE-FE acid w/336 gals. chemical & 1500# salt. ATP 2250# @ 5 bpm. MTP 2763# @ 5.2 bpm. 1st block increase 167#. 2nd 50#. 3rd 110#. ISIP 1936#. 5 min. 1690#. 10 min. 1447#. 15 min. 1210#. 1 hr. 536#. RU swab. FFL 3800'.

9/06/97 FL @ 3300'. Release pkr. POH & LD pkr. RIH w/2-7/8" tbg. SN @ 4424'. Set TAC w/12,000# tension. ND BOP. NU WH. RIH w/rods & 2-1/2" x 1-3/4" x 20' pump. Left well pumping to Battery "B". RDMO.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Mary Jo Turner TITLE Production Tech II DATE January 14, 2002
TYPE OR PRINT NAME Mary Jo Turner TELEPHONE NO. (505) 392-9797

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE JAN 28 2002

DATE _____

DATE _____

DATE _____